



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

August 28, 2025

25V548

J.S. (Jurassic) Park
Kia America, Inc.
111 Peters Canyon Road
Irvine, CA 92606-1790

Subject: Loss of Drive Power from Loose Engine Bolts

Dear J.S. (Jurassic) Park:

This letter serves to acknowledge Kia America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

KIA/SORENTO/2025
KIA/K4/2025

Mfr's Report Date: August 25, 2025

NHTSA Campaign Number: 25V548

Components:

ENGINE AND ENGINE COOLING:CRITICAL FASTENERS

Potential Number of Units Affected: 30

Problem Description:

Kia America, Inc. (Kia) is recalling certain 2025 K4 and Sorento vehicles. The connecting rod bolts in the engine may have been improperly tightened, which can cause a loss of drive power.

Consequence:

A loss of drive power increases the risk of a crash.

Remedy:

Dealers will replace the sub engine assembly, free of charge. Owner notification letters are expected to be mailed September 12, 2025. Owners may contact Kia customer service at 800-333-4542. Kia's number for this recall is SC349.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Kia America, Inc.'s contact for this recall will be Emily Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement