



U.S. Department of Transportation

**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 03, 2025

25V558

Sarah Atchison
Midwest Fire Equipment & Repair Company
901 Commerce Road
PO Box 524
Luverne, MN 56156

Subject: Rear Hose Reel Assembly May Detach from Fire Truck

Dear Sarah Atchison:

This letter serves to acknowledge Midwest Fire Equipment & Repair Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MIDWEST FIRE/ALL-POLY SERIES/2021-2025

Mfr's Report Date: August 28, 2025

NHTSA Campaign Number: 25V558

Components:

EQUIPMENT

Potential Number of Units Affected: 36

Problem Description:

Midwest Fire Equipment & Repair Company (Midwest Fire) is recalling certain 2021-2025 All-Poly Series fire trucks. The hose reel mounting plate may crack and fail, which can cause the hose reel to detach from the vehicle.

Consequence:

A hose reel that detaches can become a road hazard and increase the risk of a crash. In addition, the mounting plate can fail suddenly during hose operation, increasing the risk of injury.

Remedy:

The remedy is currently under development. Owner notification letters are expected to be mailed September 26, 2025. Owners may contact Midwest Fire's customer service at 1-800-344-2059.



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please ensure the following requirements are met:**Chronology Not Supplied**

As required by 49 CFR §573.6, provide a chronology of all principal events that were the basis for the determination that the defect related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information (such as the number of deaths and/or injuries) with their dates of receipt. In the case of a noncompliance, provide the test results and other information used to determine the existence of the noncompliance, including the date of each test and observation that indicated that a noncompliance might or did exist. Submit this information through an amended Part 573 report through the recalls portal. If additional space is needed, please upload as a separate miscellaneous document.

AMENDED 573 REQUIRED.

Involved Component Not Supplied

Provide the part number, name and description of the component(s) involved in this recall as required by 49 USC § 30119 in an amended 573 in the "Involved Components" section through the NHTSA Recalls Portal.

AMENDED 573 REQUIRED.

Remedy Not Supplied

Provide a description of the recall remedy as required by 49 CFR §573.6(8)(i), in an amended Part 573 Recall Report through the NHTSA Recalls Portal.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Midwest Fire Equipment & Repair Company's contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement