



U.S. Department of Transportation

**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 01, 2025

25V812

Dalton Jones
Newell Coach Corp.
3900 N Main St.
Miami , OK 74354

Subject: Incorrect Weld May Cause Seat Failure/FMVSS 207, 210

Dear Dalton Jones:

This letter serves to acknowledge Newell Coach Corp.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NEWELL/P50/2022

Mfr's Report Date: November 24, 2025

NHTSA Campaign Number: 25V812

Components:

SEATS

Potential Number of Units Affected: 3

Problem Description:

Newell Coach Corp. (Newell) is recalling certain 2022 P50 coaches. The pedestal mounting plate may have been improperly welded, causing the plate to separate and the seat assembly to loosen or detach. As such, these seat assemblies fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) numbers 207, "Seating Systems" and 210, "Seat Belt Assembly Anchorages."

Consequence:

A loose or detached seat assembly may not restrain the occupant as intended, increasing the risk of injury during a crash.

Remedy:

Newell will inspect for a missing weld and replace the pedestal seat as necessary, free of charge. Owner notification letters are expected to be mailed December 2, 2025. Owners may contact Newell

customer service at 1-888-363-9355.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

We have received Newell's proposed owner notification letter and it is approved for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Newell Coach Corp.'s contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement