



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

December 18, 2025

25V864

Greg Gunther
Mercedes-Benz USA, LLC
13470 International Parkway
Jacksonville, FL 32218

Subject: Incorrect Seat Belt Installed/FMVSS 208, 209

Dear Greg Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/GLE 350 4MATIC/2025-2026

Mfr's Report Date: December 12, 2025

NHTSA Campaign Number: 25V864

Components:

SEAT BELTS:REAR/OTHER

Potential Number of Units Affected: 82

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2025-2026 GLE 350 4MATIC vehicles. The center rear seat belts may have been installed without the child seat protection function and fail to lock a child restraint properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection," and FMVSS number 209, "Seat Belt Assemblies."

Consequence:

In the event of a crash, an insufficiently restrained child has an increased risk of injury.

Remedy:

Dealers will replace the center rear seat belt assembly, free of charge. Owner notification letters are expected to be mailed February 9, 2026. Owners may contact MBUSA customer service at 1-800-367-



6372. Vehicle Identification Numbers (VINs) involved in this recall will be searchable on NHTSA.gov beginning December 19, 2025.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Mercedes-Benz USA, LLC's contact for this recall will be Dusty Gardner who may be reached by email at dusty.gardner@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement