

Part 573 Safety Recall Report

25V-005

Manufacturer Name : Forest River, Inc.**Submission Date :** FEB 13, 2025**NHTSA Recall No. :** 25V-005**Manufacturer Recall No. :** 53-1883**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 396

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Forest River Inc. Spirit Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined by using the vendors sales and shipment records of when the affected cooktops were delivered to the manufacturing plant.

2025 SPIRIT SBT5260BH 2

2025 SPIRIT SBT5250BHS 8

2025 SPIRIT SBT5210CK 4

2025 SPIRIT SBT5320BEDS 10

2025 SPIRIT SBT5260RBS 8

2025 SPIRIT SBT310QB 19

Production Dates : JUN 21, 2024 - DEC 20, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2025-2025 Forest River Inc. Shasta Oasis Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined by using the vendors sales and shipment records of when the affected cooktops were delivered to the manufacturing plant.

Model year	Product name	Unit item	USA
2025	SHASTA OASIS SST31QB	100	
2025	SHASTA OASIS SST525BHS	71	
2025	SHASTA OASIS SST526BH	12	
2025	SHASTA OASIS SST526DB	11	
2025	SHASTA OASIS SST526RBS	43	
2025	SHASTA OASIS SST530QB	45	
2025	SHASTA OASIS SST532BEDS	63	

Production Dates : JUN 21, 2024 - DEC 20, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : According to the recall 24E105 filed by InVision: "The center internal aluminum burner tube connecting the gas valve to the cook top burners can be fractured."

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : According to the recall 24E105 filed by InVision: "If the burner tube is fractured, it could leak propane when the top burner gas valve is opened to use the appliance. If ignited the propane could result in a fire and/or explosion which could result in personal injury." Forest River recommends not using the cooktop until the remedy can be performed.

Description of the Cause : Unknown

Identification of Any Warning that can Occur : An owner may notice the odor of LP gas and/or the LP gas detector may alarm.

Involved Components :

Component Name 1 : LP Line

Component Description : LP Line

Component Part Number : Unknown

Supplier Identification :

Component Manufacturer

Name : Dicor/InVision
Address : 2965 Lavanture Place
Elkhart Indiana 46514
Country : United States

Chronology :

On February 12, 2025, Forest River received new remedy instructions from the vendor which include inspection of the burner tube. On February 13, 2025, Forest River amended the recall to reflect this information and updated the dealer letter as well as the remedy instructions. All Dealer's have been notified.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the inspection to determine if there are cracks and if so, perform the remedy to replace the internal gas line.

What is the Forest River Customer Service Phone Number? (574)
821-1311

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.
Please send the service invoice to the following address:

Shasta
105 14th St.
Middlebury, IN 46540

How Remedy Component Differs from Recalled Component : Unknown
Dicor/InVision - (574) 264-2699
2965 Lavanture Place
Elkhart, Indiana 46514

Identify How/When Recall Condition was Corrected in Production : Unknown.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : FEB 22, 2025 - FEB 22, 2025

Planned Owner Notification Date : FEB 22, 2025 - FEB 22, 2025

* NR - Not Reported