

Part 573 Safety Recall Report

25V-029

Manufacturer Name : Winnebago Towable

Submission Date : JAN 23, 2025

NHTSA Recall No. : 25V-029

Manufacturer Recall No. : CAM0000041



Manufacturer Information :

Manufacturer Name : Winnebago Towable

Address : 201 14th Street

Middlebury IN 46540

Company phone : 825-5250

Population :

Number of potentially involved : 144

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Winnebago Minnie

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying the production dates.

Production Dates : APR 02, 2024 - DEC 02, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain Winnebago vehicles the cooktop flame may invert when the furnace is simultaneously running.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : There is potential when the cooktop and furnace are operated at the same time the cooktop burner flame may invert. This could lead to an increased risk of personal injury or fire.

Description of the Cause : The cooktop is installed where it is not sealed completely from the furnace.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Furnace

Component Description : 30000BTU DFMD30111

Component Part Number : 261436

Supplier Identification :

Component Manufacturer

Name : Winnebago Ind Inc.

Address : 201 14th Street

Middlebury Indiana 46540

Country : United States

Chronology :

In mid-December, Product Safety was notified of two separate claims involving the cooktop flame becoming inverted when the furnace was running simultaneously. An investigation was subsequently opened. During the investigation, the concern was replicated on a unit on campus, which led to an internal hold notice being initiated. It was discovered there wasn't full separation between the cooktop and furnace.

The Product Safety Committee met January 16, 2025, and decided the issue presented an unreasonable risk to safety and a recall was initiated.

Winnebago is aware of 2 claims, 0 injuries, and no property damage as a result of this condition.

Description of Remedy :

Description of Remedy Program : Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : The remedy will involve installing a panel to provide full separation between the cooktop and furnace.

Identify How/When Recall Condition was Corrected in Production : Production began installing a panel to provide full separation between the cooktop and furnace.

Recall Schedule :

Description of Recall Schedule : Recall notifications will follow the 60 day requirement.

Planned Dealer Notification Date : FEB 12, 2025 - FEB 12, 2025

Planned Owner Notification Date : MAR 23, 2025 - MAR 23, 2025

* NR - Not Reported