

Part 573 Safety Recall Report

25V-171

Manufacturer Name : Thor Motor Coach**Submission Date :** MAR 19, 2025**NHTSA Recall No. :** 25V-171**Manufacturer Recall No. :** RC000325**Manufacturer Information :**

Manufacturer Name : Thor Motor Coach

Address : PO Box 1486

701 County Road 15 Elkhart IN 46515

Company phone : 877-500-1020

Population :

Number of potentially involved : 4,251

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2026 Thor Motor Coach Axis, Chateau, Coleman, Echelon, Eddie Bauer, Four Winds, Freedom Elite, Freedom Traveler, Geneva, Magnitude, Outlaw, Pasadena, Quantum, Vegas

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 02, 2023 - MAR 11, 2025

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The slideout may have the ability to operate without the Park Brake engaged.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The slideout could deploy while the vehicle is in motion which could lead to obstructed view and potentially lead to an accident, property damage, and/or personal injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : With the engine running, the transmission in park, and the parking brake disengaged, attempt to cycle the slideout rooms. If the slideout moves then the wire harness is miswired. Do not push the slideout button while the vehicle is in motion.

Involved Components :

Component Name 1 : Park Brake harness

Component Description : Ford Park Brake harness

Component Part Number : 0526855

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

3/10 – TMC wire harness department identified the park brake wire harness pinning was incorrect for the E350 & E450 products.

3/11 – TMC engineering drafted and published an updated print for production.

3/11 – TMC engineering generated a product scope based on the release of the incorrect print.

3/14 – TMC safety committee voted for a recall to correct all affected products

Description of Remedy :

Description of Remedy Program : TMC will replace the incorrect park brake harness free of charge to owners. Reimbursement will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : The Park Brake harness (TMC p/n 0526855) should be wired/pinned in a manner that will not allow the slideout to operate while the Park Brake is disengaged.

Identify How/When Recall Condition was Corrected in Production : The wire harness department discovered the incorrect park brake harness production on 3/10/2025. Starting on 3/11/2025 engineering drafted and published an updated print to correct the defect.

Recall Schedule :

Description of Recall Schedule : Thor Motor Coach has the utmost urgency in notifying owners about a recall that affects their vehicle. Letters will be sent out once all pertinent information has been gathered.

Planned Dealer Notification Date : MAY 05, 2025 - MAY 05, 2025

Planned Owner Notification Date : MAY 05, 2025 - MAY 05, 2025

* NR - Not Reported