



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V247

Manufacturer Name: BMW of North America, LLC

Submission Date: Apr 21, 2025

NHTSA Recall No.: 25V247

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: BMW of North America,
LLC
Address: P.O. Box 1227
Westwood NJ, 07675-1227

Total number of potentially involved: 26
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 BMW X3 30 xDrive

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Feb 19, 2025 - Feb 19, 2025

Number of potentially involved:

Descriptive Information:

Approximately 26 vehicles have been manufactured with front brake discs that may have been damaged during the supply chain transport process.

Basis for recall population determination: Vehicle assembly information and supplier production records were used to determine the specific dates of potentially affected vehicles.

Recall component difference to non-recall component: The front brake discs may have been damaged during the supply chain transport process.

Defect / Noncompliance Description

Description of the defect or noncompliance:

This safety recall involves the front brake discs, which may have been damaged during the supply chain transport process. Damage, in the form of heavy marks or cuts to the disc surface, was present. If this happened then, during hard braking, further damage could occur, which could affect front brake performance.

Part 573 Safety Recall Report

25V247

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

This could increase the risk of a crash.

Description of the cause:**Identification of any warning that can occur:**

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:** ZF Foxconn Chassis Modules**Address:** 191 Parkway West
Gray Court SC, 29334**Country:** United States

Involved Components

Component Name 1: Front Brake Disc**Component Description:** Front Brake Disc**Component Part Number:** 8831512-01

Chronology

On February 20, 2025, during a quality check at a vehicle assembly plant, an acoustic abnormality was noticed on a Model Year 2025 BMW X3 xDrive 30. Initial observations indicated that it was located in the area of a front brake disc. It was suggested that it was an isolated case, as no other vehicles, which undergo similar quality checks, were observed with a similar noise pattern. On March 24th, an unusual and similar noise was noticed on a Model Year 2025 BMW X3 xDrive 30 at a BMW center. A vehicle inspection revealed a damaged front brake disc. On March 27th, an engineering investigation was initiated. Reviews indicated that the two vehicles contained front brake discs from the same supplier production lot. The supplier was contacted. Reviews of supplier production records did not reveal any production deviations. However, further reviews indicated that damage could have occurred during the supply chain transport process. A review of supply chain records was performed to identify potentially

Part 573 Safety Recall Report

25V247

suspect parts. Vehicle assembly information and supplier production records were reviewed to determine the number and production dates of potentially affected vehicles. On April 9, 2025, BMW decided to conduct a voluntary safety recall. BMW is not aware of any warranty claims, customer complaints, or field reports related to this issue. BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The front brake discs and brake pads will be replaced.

Owners will be notified by First Class mail and instructed to take their vehicle to an authorized BMW dealer to have the remedy performed for free. If this condition were noticed on a potentially affected vehicle prior to this recall, the remedy would be covered by the BMW New Vehicle Limited Warranty program. Therefore, reimbursement for a pre-notification remedy re Part 573.13 and Part 577.11 is not necessary.

How remedy component differs from recalled component:

Recalled Component: Front Brake Disc; p/n –8831512-01

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Part 573 Safety Recall Report**25V247****Description of recall schedule:**

Dealer notification is planned to begin and end on April 16, 2025.
Owner notification is planned to begin and end on June 6, 2025.

Planned Dealer Notification Date: Apr 16, 2025 - Apr 16, 2025

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jun 06, 2025 - Jun 06, 2025

Phased Recall

Date when VIN will be searchable: