

# Part 573 Safety Recall Report

# 25V-296

**Manufacturer Name :** Shyft Group**Submission Date :** MAY 07, 2025**NHTSA Recall No. :** 25V-296**Manufacturer Recall No. :** 25-10**Manufacturer Information :**

Manufacturer Name : Shyft Group

Address : 1541 Reynolds Road  
Charlotte MI 48813

Company phone : 517-543-6400

**Population :**

Number of potentially involved : 6

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2025-2025 Utilmaster Aeromaster

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Vehicles subject to this recall are equipped with rear seats to be used for training delivery drivers. Vehicles not subject to this recall are not equipped with the rear, training seats.

Production Dates : MAR 07, 2025 - APR 22, 2025

VIN Range 1 : Begin : 4UZAAPFD0SCVS1995 End : 4UZAAPFD4SCVS2003  Not sequential**Description of Defect :**

Description of the Defect : Rear training designated seating positions are not equipped with seat belts.

FMVSS 1 : 208 - Occupant crash protection

FMVSS 2 : NR

Description of the Safety Risk : A designated seating position which does not have a seat belt for the occupant could increase the risk of that occupant during a crash.

Description of the Cause : Supplier changed offering a seat and seat belt as one kit to seat and seat belts as individual kits.

Identification of Any Warning that can Occur : There is no warning associated with a missing seat belt.

**Involved Components :**

Component Name 1 : Seat Belt

Component Description : Type 1 Seat Belt

Component Part Number : 21316162

## Supplier Identification :

### Component Manufacturer

Name : Freedman Seating Company

Address : 4545 W. Augusta

Chicago Illinois 60651

Country : United States

## Chronology :

On April 30, 2025, Product Safety and Compliance received customer complaint indicating they had received a unit without seat belts at the rear, designated seating positions. An immediate stop ship was issued for units believed to be in Shyft's possession. Between May 1 and May 2 Shyft confirmed the number of vehicles outside of its possession and determined that a non-compliance could exist in the affected population.

## Description of Remedy :

Description of Remedy Program : The required seat belts will be sent and installed in the affected vehicles at no charge. These vehicles are still within their warranty period and any remedial actions related to the seat belt installation would be done at no charge.

How Remedy Component Differs from Recalled Component : Rear seats in vehicles with the remedy will have seat belts while seats in the recalled vehicles will not.

Identify How/When Recall Condition was Corrected in Production : As a part of the stop ship process, seat belts were installed in vehicles at Shyft on May 1.

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 08, 2025 - MAY 09, 2025

Planned Owner Notification Date : MAY 14, 2025 - MAY 14, 2025

\* NR - Not Reported