



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V305

Manufacturer Name: DRV Suites

Submission Date: May 09, 2025

NHTSA Recall No.: 25V305

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: DRV Suites

Address: 1000 Interchange Drive
PO Box 235
Howe IN, 46746

Total number of potentially involved: 16

Estimated percentage with defect: 10%

Vehicle Information

Vehicle 1: 2024-2025 DRV Full House

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Jun 11, 2024 - Feb 05, 2025

Number of potentially involved:

Descriptive Information:

Recall Population was determined by the information provided by MorRyde International, Inc. as to the date range involved and parts provided to production.

Defect / Noncompliance Description

Description of the defect or noncompliance:

It has been decided that vehicles in the recall population may have a MorRyde step that have clip on brackets to hold a removable step. MorRyde has found a potential issue where the receiver for the step that is installed on these brackets was not manufactured with the required thread locking compound.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

25V305

Absence of the thread locking compound may allow the receiver to come lose and disengage from the bracket. If this happens during use it may result in fall and personal injury.

Description of the cause:

MorRyde manufacturing did not properly install the thread locking compound during production.

Identification of any warning that can occur:

The receiver on the bracket can be spun which can cause it to unscrew and detach from the installed bracket.

Component Manufacturer

Tier of Supplier:**Supplier Type:**

Name: MorRyde international

Address: 1966 Sterling Ave
Elkhart IN, 46516

Country: United States

Involved Components

Component Name 1: clip on bracket

Component Description: clip on bracket for removable step

Component Part Number: STP57-515/999 and STP57-641/999

Chronology

5-2-25 received 573 and letter from MorRyde with part numbers affected, 5-7-25 finalized recall population. 5-7-25 safety committee voted.

Related NHTSA Recall Number:

Part 573 Safety Recall Report

25V305

Description of Remedy

Remedy Type: Repair**Consumer Advisories:** Do Not Drive Park Outside**Description of remedy program:**

MorRyde has designed a new bracket that can be installed on units that are involved.

How remedy component differs from recalled component:

The remedy components will be verified to have the required thread locking fluid

Identify how/when recall condition was corrected in production:

As of April 25, 2025 MorRyde has corrected the parts supplied.

Reimbursement Plan

Description of reimbursement program:**Period of reimbursement:****Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Mailing will begin once approval is received

Planned Dealer Notification Date: Jun 27, 2025 - Jun 27, 2025 No Dealers

Part 573 Safety Recall Report

25V305

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jun 27, 2025 - Jun 27, 2025

Phased Recall

Date when VIN will be searchable: