



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V320

Manufacturer Name: Winnebago Industries, Inc.

Submission Date: Jun 27, 2025

NHTSA Recall No.: 25V320

Manufacturer Recall No.: 196

Manufacturer Information

Population

Manufacturer Name: Winnebago Industries, Inc.

Address: PO BOX 152
605 W. Crystal Lake Rd.
Forest City IA, 50436

Total number of potentially involved: 57

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2023-2024 Winnebago Commercial Vehicle

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 08, 2024 - Mar 28, 2025

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates after receiving a letter from the manufacture of the recalled component (MORryde) regarding the issue.

Defect / Noncompliance Description

Description of the defect or noncompliance:

This is a bracket that is used on the side of an RV that has a receiver for a removable step assembly to clip into. This receiver installed using a thread locking fluid to retain the assembly. It was found that there are parts that did not have this thread locking compound installed during assembly.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If this receiver becomes loose while being used, it can disengage from the fastener that is used to assemble it to the bracket and disconnect from the bracket allowing the step assembly to fall from its

Part 573 Safety Recall Report

25V320

use location. This has the potential to cause personal injury if the step is being used when this happens.

Description of the cause:

Failure to use thread locking fluid during the assembly process.

Identification of any warning that can occur:

The receiver on the bracket can be spun which can cause it to unscrew and detach from the installed bracket.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: MORryde International Inc.

Address: 1966 Sterling Avenue
Elkhart IN, 46540

Country: United States

Involved Components

Component Name 1: Step Bracket

Component Description: Bracket - Mounting - Step - Folding Patio

Component Part Number: STP57-515

Chronology

Winnebago was notified by MORryde on 4/17/2025 and an internal hold was placed for units on campus. After reviewing purchase orders and build dates, scope was determined. An internal email notifying the Product Safety Committee of the decision to recall was sent 5/14/2025.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Repair, Replace

Part 573 Safety Recall Report

25V320

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

The remedy components will be verified by MORryde to have the required thread locking fluid. Dealers will be instructed to inspect, repair, and replace, if necessary, the clip-on brackets.

Identify how/when recall condition was corrected in production:

Winnebago reviewed and quarantined any recalled stock. MORryde is supplying new stock that has been verified to meet their requirements.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Recall schedule for notifications will be within the 60 day requirement.

Planned Dealer Notification Date: Jul 11, 2025 - Jul 11, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Jul 11, 2025 - Jul 11, 2025 Phased Recall

Date when VIN will be searchable: