



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 25V408

**Manufacturer Name:** Winnebago Towable

**Submission Date:** Jul 28, 2025

**NHTSA Recall No.:** 25V408

**Manufacturer Recall No.:** CAM0000043

### Manufacturer Information

### Population

**Manufacturer Name:** Winnebago Towable

**Address:** 201 14th Street  
Middlebury IN, 46540

**Total number of potentially involved:** 527

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2025-2025 Winnebago Micro Minnie

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Oct 07, 2024 - Apr 07, 2025

**Number of potentially involved:** 514

**Descriptive Information:**

The recall population was determined by identifying the production dates.

**Vehicle 2:** 2025-2025 Winnebago Micro Minnie FLX

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Oct 07, 2024 - Apr 07, 2025

**Number of potentially involved:** 13

**Descriptive Information:**

The recall population was determined by identifying the production dates.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

# Part 573 Safety Recall Report

# 25V408

On certain Winnebago vehicles the cooktop flame may invert when the furnace is simultaneously running.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

There is potential when the cooktop and furnace are operated at the same time the cooktop burner flame may invert. This could lead to an increased risk of personal injury or fire.

**Description of the cause:**

The cooktop is installed where it is not sealed completely from the furnace.

**Identification of any warning that can occur:**

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:** OEM

**Name:** Winnebago of Indiana

**Address:** 201 14th Street  
Middlebury IN, 46567

**Country:** United States

## Involved Components

**Component Name 1:** Cooktop

**Component Description:** 2 Burner Cooktop

**Component Part Number:** 282491

## Chronology

In late January a recall was launched on the Winnebago 2025 Minnie model series due to the cooktop flame potentially inverting due to the furnace. On February 11 customer service received a complaint from a dealership on a 2025 Micro Minnie model experiencing the same concern. An investigation was subsequently opened.

# Part 573 Safety Recall Report

# 25V408

During the investigation, the concern was replicated on a unit on campus, which led to production correcting the concern in early April. The Product Safety Committee met June 10, 2025, and decided the issue presented an unreasonable risk to safety and a recall was initiated. Winnebago is aware of 12 claims, 0 injuries, and no property damage as a result of this condition.

**Related NHTSA Recall Number:** This is an expansion to recall 25V029

## Description of Remedy

### Remedy Type:

**Consumer Advisories:**  Do Not Drive  Park Outside

### Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

### How remedy component differs from recalled component:

The remedy will involve installing a panel to provide full separation between the cooktop and furnace.

### Identify how/when recall condition was corrected in production:

Production began installing a separating shelf / panel to provide full separation between the cooktop and furnace.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

Recall notifications will follow the 60 day requirement.

**Planned Dealer Notification Date:** Aug 08, 2025 - Aug 13, 2025  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** Aug 15, 2025 - Aug 15, 2025  Phased Recall

**Date when VIN will be searchable:**