



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V412

**Manufacturer Name:** Bontrager Outdoors

**Submission Date:** Jul 29, 2025

**NHTSA Recall No.:** 25V412

**Manufacturer Recall No.:**

### Manufacturer Information

### Population

**Manufacturer Name:** Bontrager Outdoors

**Address:** 0925 North State RD 5  
Shipshewana IN, 46565

**Total number of potentially involved:** 24

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2025-2025 Bontrager Outdoors 7 Rod

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 30, 2024 - May 16, 2025

**Number of potentially involved:** 15

**Descriptive Information:**

During the first production run of this product, it came to our attention that the proper carbon monoxide detector was not installed in the campers. We identified these units when our Quality Control personnel alerted management about the missing component. Any camper manufactured after May 16th, 2025, has the proper detector installed on the production line.

**Vehicle 2:** 2025-2025 Skinny Guy Campers Armor 7 LT

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Aug 16, 2024 - May 16, 2025

**Number of potentially involved:** 9

**Descriptive Information:**

During the first production run of this product, it came to our attention that the proper carbon monoxide detector was not installed in the camper. We identified these units when our Quality Control personnel alerted management about the missing component. Any camper manufactured after May 16th, 2025, has the proper detector installed on the production line.

# Part 573 Safety Recall Report

# 25V412

## Defect / Noncompliance Description

### Description of the defect or noncompliance:

Production failed to install carbon monoxide detectors in the camper. Their reasoning was there no LP gas source to generate the risk.

**FMVSS1:**

**FMVSS2:**

### Description of the safety risk, including crash, fire, death, injury:

The owner could suffer possible side effects of inhaling carbon monoxide increasing the risk of injury.

### Description of the cause:

### Identification of any warning that can occur:

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:** BRK CO250RVA

**Component Description:** Carbon Monoxide detector

**Component Part Number:** 95-10000-A

## Chronology

No real event preceding this decision, following RVIA Guideline is how we put this back into compliance. We had a change in the Quality Control department and the new QC person spotted the issue.

# Part 573 Safety Recall Report

# 25V412

Related NHTSA Recall Number:

## Description of Remedy

**Remedy Type:** Repair

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

We are allotting time for each Dealer to install these detectors for the retail customers and their stock units.

**How remedy component differs from recalled component:**

There was no Carbon Monoxide detector, so we are supplying the detectors and the labor hours to remediate the issue.

**Identify how/when recall condition was corrected in production:**

Any unit produced after May 16th 2025 will have the detector installed by default.

## Reimbursement Plan

**Description of reimbursement program:**

1. Repair time .2 hours
2. We are sending the detector to honor the warranty/nonconformance.

**Period of reimbursement:**

Until all units are completed.

**Costs to be reimbursed:**

Labor cost of .2 hours depending on individual shop rates.

**Address for reimbursement claims:**

925 State Road 5  
Shipshewana IN, 46565

## Recall Schedule

**Description of recall schedule:**

1. Affected Dealer get the first round of letters.

**Part 573 Safety Recall Report****25V412**

2. Retail customers will get their letters one week after.

**Planned Dealer Notification Date:** Aug 11, 2025 - Aug 15, 2025

No Dealers

**Planned Interim Owner Notification Date:** Aug 11, 2025 - Aug 15, 2025

No Owners

**Planned Remedy Owner Notification Date:**

Phased Recall

**Date when VIN will be searchable:**