



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V499

Manufacturer Name: Winnebago Industries, Inc.

Submission Date: Aug 04, 2025

NHTSA Recall No.: 25V499

Manufacturer Recall No.: 200

Manufacturer Information

Population

Manufacturer Name: Winnebago Industries, Inc.

Address: PO BOX 152
605 W. Crystal Lake Rd.
Forest City IA, 50436

Total number of potentially involved: 655

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2025 WINNEBAGO EKKO

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jun 06, 2023 - Feb 27, 2025

Number of potentially involved: 655

Descriptive Information:

The population was determined by the production dates.

Defect / Noncompliance Description

Description of the defect or noncompliance:

On certain Winnebago Motorhomes, the tire valve extensions for the inner wheels may get damaged by contact with the outer wheels. In the event this happens, the inner tire could gradually lose air pressure.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

There is potential the outer tire could overload and cause it to fail.

Description of the cause:

Part 573 Safety Recall Report

25V499

During production, the valves were not bent as required to avoid contact with the outer wheel.

Identification of any warning that can occur:

The tire valve extensions will show chaffing due to contact with the outer wheel.

Component Manufacturer

Tier of Supplier:**Supplier Type:**

Name: Winnebago Industries

Address: 605 West Crystal Lake Road
Forest City IA, 50436

Country: United States

Involved Components

Component Name 1: Valve ASM

Component Description: 8" Valve Stem Assembly

Component Part Number: 000278287 / 35507401000

Chronology

In late March 2025, the Winnebago Service and Quality Teams found a discrepancy with the Tire Valve Extensions from a dealer part order. An investigation was subsequently opened to understand this issue further. Upon completion of the investigation, the Product Safety Committee met on July 28, 2025, and voted to initiate the Recall process.

At this time, Winnebago is aware of 12 claims as a result of this condition. Winnebago is not aware of any property damage or injury attributed directly or indirectly to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Part 573 Safety Recall Report

25V499

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

The remedy components will involve replacement valves that do not contact the outer wheels.

Identify how/when recall condition was corrected in production:

The recall condition was corrected in production due to the introduction of chassis supplied TPMS.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Recall schedule for notifications will be within the 60-day requirement.

Planned Dealer Notification Date: Aug 22, 2025 - Aug 27, 2025 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Oct 02, 2025 - Oct 02, 2025 ☐ Phased Recall

Date when VIN will be searchable: