



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

# Part 573 Safety Recall Report

## 25V579

**Manufacturer Name:** Cruiser RV

**Submission Date:** Sep 10, 2025

**NHTSA Recall No.:** 25V579

**Manufacturer Recall No.:** TBD

### Manufacturer Information

### Population

**Manufacturer Name:** Cruiser RV

**Address:** 7805 North State Road 9  
PO Box 130  
Howe IN, 46746

**Total number of potentially involved:** 10

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2025-2025 CRUISER AVENIR

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Sep 17, 2024 - Mar 13, 2025

**Number of potentially involved:** 10

**Descriptive Information:**

Recall population is all Avenir A-19BH travel trailers produced by Cruiser RV with and underslung axle built between 9-17-24 and 3-13-25.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

It has been decided that vehicles in the recall population have an underslung axle which does not provide adequate clearance between the tire tread and the wheel well.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

Improper clearance between the tire and the wheel well could cause excessive wear or damage of the tire. This could lead to an increased risk of tire blowout and a crash.

# Part 573 Safety Recall Report

# 25V579

## Description of the cause:

Engineering had optioned in the wrong underslung axle on the prints of the unit.

## Identification of any warning that can occur:

There may be signs of uneven wear on the tires or marks on the wheel well where the tire has made contact with the wheel well.

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:** Dexter Axle 3500 lb.

**Component Description:** Dexter 3500 lb. - underslung 5 lug

**Component Part Number:** V000113323

## Chronology

8-8-25 Notified by warranty of a possible issue with the clearance on the Cruiser Avenir A19BH travel trailers reviewed warranty claims for possible further incidents.

8-11-25 Incident logged.

8-15-25 unit returned to R & D for inspection,

8-18-25 reviewed at WIRC and elevated to the CPAC.

8-25-25 cpac reviewed and elevated to SSC.

8-29-25 SSC voted to make this a recall. Cruiser has had only one warranty claim on a dealer lot unit for the clearance issue.

**Related NHTSA Recall Number:**

## Description of Remedy

**Part 573 Safety Recall Report****25V579****Remedy Type:** Replace**Consumer Advisories:**  Do Not Drive  Park Outside**Description of remedy program:**

The remedy for this defect is to your local dealer or service provider replace the underslung axle with a over slung axle. This will provide the adequate clearance for safe travel All reimbursement will be covered under Heartland's general reimbursement plan. This will be done at no cost to the owner.

**How remedy component differs from recalled component:**

The underslung axle will be replaced with a Lippert V000315474 over slung axle.

**Identify how/when recall condition was corrected in production:**

As of March 13, 2025 Cruiser RV is no longer making the Avenir A-19BH

**Reimbursement Plan**

Manufacturer used general reimbursement plan on file.

**Recall Schedule****Description of recall schedule:**

Mailing will begin once approval is received

**Planned Dealer Notification Date:** Oct 30, 2025 - Oct 30, 2025  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** Oct 30, 2025 - Oct 30, 2025  Phased Recall

**Date when VIN will be searchable:**