



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V610

Manufacturer Name: Forest River, Inc.

Submission Date: Sep 12, 2025

NHTSA Recall No.: 25V610

Manufacturer Recall No.: 53-1974

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 502

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 FOREST RIVER SPIRIT

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: May 20, 2025 - Sep 04, 2025

Number of potentially involved: 14

Descriptive Information:

The scope was determined by the start date of a new employee.

Vehicle 2: 2025-2025 FOREST RIVER SPIRIT

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Mar 20, 2025 - Sep 04, 2025

Number of potentially involved: 32

Descriptive Information:

The scope was determined by the start date of a new employee.

Vehicle 3: 2026-2026 FOREST RIVER SHASTA OASIS

Product Category: Trailers

Part 573 Safety Recall Report

25V610

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Mar 17, 2025 - Sep 05, 2025

Number of potentially involved: 182

Descriptive Information:

The scope was determined by the start date of a new employee.

Vehicle 4: 2025-2025 FOREST RIVER SHASTA OASIS

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Mar 17, 2025 - Sep 05, 2025

Number of potentially involved: 274

Descriptive Information:

The scope was determined by the start date of a new employee.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The wire sheathing to the 30AMP or 50AMP inlet may have been stripped inconsistently.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Inconsistent sheathing removal may allow for arcing, which may lead to a fire and property damage.

Description of the cause:

Manufacturing Error.

Identification of any warning that can occur:

A user may notice the vehicle not having power when plugged into shore power.

Component Manufacturer

Part 573 Safety Recall Report**25V610****Tier of Supplier:****Supplier Type:****Name:****Address:****Country:****Involved Components****Component Name 1:** 110V WIRING**Component Description:** 110V WIRING**Component Part Number:** N/A**Chronology**

On September 4, 2025, during a routine Standards Manager Audit of the manufacturing plant, it was discovered that the wire sheathing to either the 30AMP or 50AMP inlet may have been stripped inconsistently.

On September 8, 2025, Forest River's Office of Corporate Compliance ("OCC") was notified, and a research item was opened into the concern.

On September 12, 2025, Forest River's Corporate Committee voted to recall. A Stop Sale Notice is being issued.

Related NHTSA Recall Number:**Description of Remedy****Remedy Type:** Repair**Consumer Advisories:** Do Not Drive Park Outside**Description of remedy program:**

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy and correct the wiring at the 30AMP or 50AMP inlet.

What is the Forest River Customer Service Phone Number? (574) 825-0856

Part 573 Safety Recall Report**25V610**

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Shasta
105 14th St.
Middlebury, IN 46540

How remedy component differs from recalled component:

Affected Component – 110V Wiring
Replacement Component – 110V Wiring
The wiring will now have the proper amount of sheathing

Identify how/when recall condition was corrected in production:

During the week of September 8, 2025, the manufacturing plant was trained by the Standards Manager and all vehicles in Forest River control were inspected and repaired as necessary.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Oct 22, 2025 - Oct 22, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Oct 22, 2025 - Oct 22, 2025 Phased Recall

Date when VIN will be searchable: