



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V624

Manufacturer Name: Hyundai Motor America

Submission Date: Sep 29, 2025

NHTSA Recall No.: 25V624

Manufacturer Recall No.: 028G

Manufacturer Information

Population

Manufacturer Name: Hyundai Motor America

Address: 10550 Talbert Avenue
Fountain Valley CA, 92708

Total number of potentially involved: 7,855

Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2023-2025 GENESIS GV60

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Electric Battery Power

Production Dates: Feb 04, 2022 - Jul 01, 2024

Number of potentially involved: 7,855

Descriptive Information:

The affected vehicles include certain model year 2023-2025 Genesis GV60 vehicles produced on the specified dates by Hyundai Motor Company ("HMC") for sale in the U.S.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The stainless-steel upper molding at the top of the windshield assembly in the subject vehicles may have been produced at the supplier with insufficient adhesion, increasing the risk of detachment in certain driving scenarios.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Detachment of the molding while driving can create road hazards for other drivers and increase the risk of a crash.

Part 573 Safety Recall Report

25V624

Description of the cause:

Inadequate control of laminating temperature and insufficient caulking during the supplier manufacturing process.

Identification of any warning that can occur:

Occupants may detect wind noise, whistling, and/or knocking in the upper windshield area of their vehicle while driving.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: KEUMGANG CHEMICAL

Address: 1472, Nakdong-daero
Sasang-gu
Busan Foreign States

Country: Korea, Republic Of

Involved Components

Component Name 1: Molding-Windshield Glass UPR

Component Description: Windshield Glass Upper Molding

Component Part Number: 86121CU000

Chronology

October 2022 - February 2025

- October 26, 2022 – HMNA received a field report indicating a peeling condition involving the windshield's chrome upper molding on a model year 2023 GV60 vehicle in the U.S. market. HMNA's North America Safety Office ("NASO") began monitoring field information for emerging trends of similar reports.

March 2025 - September 2025

- March 13, 2025 – HMC informed NASO of an emerging overseas investigation regarding the subject condition.
- March 14, 2025 – NASO initiated a new investigation into the subject condition and began tracking and analyzing market field information.
- July 29, 2025 – NASO conducted testing of warranty part returns at its Safety Test & Investigation Laboratory ("STIL") and replicated the failure mechanism (delamination of the molding bond to the

Part 573 Safety Recall Report

25V624

windshield during driving).

- August through early September 2025 – NASO requested manufacturing records to confirm manufacturing changes involving the windshield/trim bonding processes.
- September 11, 2025 – NASO convened it's North America Safety Decision Authority ("NASDA") to review its findings and decided to conduct a safety recall of potentially affected U.S. market vehicles.
- As of the date of this filing, HMNA is aware of 112 unique reports of detachment received from October 26, 2022, through August 8, 2025, from affected vehicles in the U.S. market. There are no crashes, injuries, fatalities, or fires related to the recall condition in the U.S.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Genesis retailer for replacement of the windshield upper molding. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Genesis New Vehicle Limited Warranty. Additionally, Genesis will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on February 22, 2024.

How remedy component differs from recalled component:

The remedy moldings are manufactured with proper lamination temperature control and caulking.

Identify how/when recall condition was corrected in production:

The lamination control equipment was improved and caulking added by July 2024.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Dealers will be notified electronically by the specified dates.

Part 573 Safety Recall Report**25V624**

Owners will be notified via certified mail by the specified dates.

Planned Dealer Notification Date: Nov 17, 2025 - Nov 17, 2025

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Nov 17, 2025 - Nov 17, 2025

Phased Recall

Date when VIN will be searchable: Sep 20, 2025