



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V641

Manufacturer Name: International Motors, LLC

Submission Date: Sep 25, 2025

NHTSA Recall No.: 25V641

Manufacturer Recall No.: 25516

Manufacturer Information

Population

Manufacturer Name: International Motors, LLC

Address: 2701 Navistar Drive
Lisle IL, 60532

Total number of potentially involved: 3

Estimated percentage with defect: 20%

Vehicle Information

Vehicle 1: 2026-2026 IC BUS CECB

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Coach

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: May 12, 2025 - May 13, 2025

Number of potentially involved: 3

Descriptive Information:

The suspect population was identified by commercial buses equipped with windshield wiper modules supplied by CVG.

The inclusive dates of manufacture were determined by suspect wiper module date codes provided by CVG and production data at IC Bus's manufacturing plant.

The vehicles in the suspect population may have been built with wiper modules with suspect date codes and all other similar vehicles were not.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The wiper module crank-shaft assembly is not welded properly which can cause the left-side windshield wiper to not wipe the windshield.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

25V641

An inoperative left-side windshield wiper may reduce visibility in certain driving conditions, increasing the risk of a crash.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: Other

Name: CVG

Address: 527 W HWY 20
Michigan City IN, 46360

Country: United States

Involved Components

Component Name 1: Wiper, W/S, Elect

Component Description: Wiper Module Assembly

Component Part Number: 4279110C94

Chronology

08/27/2025 Notified by Tulsa Bus plant that 2 buses were found with the left-side wiper not functioning.

08/29/2025 International initiates a delivery stop on school buses at the Tulsa Bus Assembly Plant and establishes the clean point.

08/29/2025 Supplier informs International that there was an issue with its crank shaft assembly welding process in March 2025 but thought it had contained all suspect parts.

09/03/2025 Supplier informs International that suspect parts were not quarantined and had been assembled into wiper modules and shipped to the Tulsa Bus Plant.

09/05/2025 Supplier finishes a review of its manufacturing records and determines that 50 pieces were assembled into 1,638 wiper modules over 24 different build lots ranging from 03/04/2025 thru 04/17/2025.

Part 573 Safety Recall Report

25V641

09/05/2025-09/17/2025 International finishes its inspection of 1,291 buses at the Tulsa Bus Assembly Plant and finds that only 229 suspect wiper modules were found.

09/15/2025 International places a quality hold on all suspect wiper modules at its Parts Distribution Centers

09/17/2025 International finalizes the suspect population.

09/19/2025 International declares a safety recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The remedy will involve replacing any wiper module found with a suspect date code.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

See chronology.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

When parts are available, remedy instructions and owner notifications will be distributed. Tentative schedule as indicated.

Planned Dealer Notification Date: Nov 17, 2025 - Nov 17, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Part 573 Safety Recall Report

25V641

Planned Remedy Owner Notification Date: Nov 24, 2025 - Nov 24, 2025 Phased Recall

Date when VIN will be searchable: Nov 17, 2025