



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V701

**Manufacturer Name:** Winnebago Towable

**Submission Date:** Oct 15, 2025

**NHTSA Recall No.:** 25V701

**Manufacturer Recall No.:** CAM0000045

### Manufacturer Information

### Population

**Manufacturer Name:** Winnebago Towable

**Address:** 201 14th Street  
Middlebury IN, 46540

**Total number of potentially involved:** 377

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2019-2019 WINNEBAGO MICRO MINNIE5

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Nov 14, 2018 - Jan 14, 2019

**Number of potentially involved:** 102

**Descriptive Information:**

The recall population was determined by pulling VIN information.

**Vehicle 2:** 2020-2020 WINNEBAGO MINNIE PLUS5

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 13, 2019 - Apr 18, 2019

**Number of potentially involved:** 6

**Descriptive Information:**

The recall population was determined by pulling VIN information.

**Vehicle 3:** 2018-2021 WINNEBAGO MINNIE

**Product Category:** Trailers

**Part 573 Safety Recall Report****25V701****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 18, 2018 - Dec 09, 2020**Number of potentially involved:** 129**Descriptive Information:**

The recall population was determined by pulling VIN information.

**Vehicle 4:** 2019-2019 WINNEBAGO MINNIE DROP**Product Category:** Trailers**Product Type:****Fuel / Propulsion:****Production Dates:** Feb 14, 2018 - Jun 04, 2018**Number of potentially involved:** 10**Descriptive Information:**

The recall population was determined by pulling VIN information.

**Vehicle 5:** 2018-2019 WINNEBAGO MICRO MINNIE**Product Category:** Trailers**Product Type:****Fuel / Propulsion:****Production Dates:** Jan 12, 2018 - Jun 04, 2018**Number of potentially involved:** 126**Descriptive Information:**

The recall population was determined by pulling VIN information.

**Vehicle 6:** 2022-2022 WINNEBAGO HIKE100**Product Category:** Trailers**Product Type:****Fuel / Propulsion:****Production Dates:** Dec 20, 2021 - Feb 14, 2022**Number of potentially involved:** 4**Descriptive Information:**

**Part 573 Safety Recall Report****25V701**

The recall population was determined by pulling VIN information.

**Defect / Noncompliance Description****Description of the defect or noncompliance:**

Certain Winnebago vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard No. 110, "Tire Selection and Rims." The Federal Identification Label and Tire Loading Information Placard has the incorrect tire size listed.

**FMVSS1:** 110 - Tire selection and rims

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

There is potential that misprinted labels could lead the vehicle operator to install a replacement tire that is too large to properly fit on the vehicle, increasing the risk of a crash

**Description of the cause:**

Incorrect information inputted into the system

**Identification of any warning that can occur:**

N/A

**Component Manufacturer**

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

**Involved Components**

**Component Name 1:** LABEL-UNIT FED TIRE 4X6

**Component Description:** LABEL-UNIT FED TIRE 4X6

**Component Part Number:** 201741130000

# Part 573 Safety Recall Report

# 25V701

## Chronology

In mid-August, Winnebago Product Safety was notified of a consumer complaint regarding their Compliance Label and Tire Loading Information Placard listing the incorrect tire size. In late September, Product Safety opened an investigation.

On October 8th, 2025, the Product Safety Committee met to review the investigation and determined a compliance concern.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

**How remedy component differs from recalled component:**

Winnebago will authorize dealership, or retail customers, to install the new Fed Tag on the off-door side of the unit.

**Identify how/when recall condition was corrected in production:**

The Federal Identification Label and Tire Loading Information Placard has been corrected in the system

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

The recall schedule will follow the 60-day requirement.

**Planned Dealer Notification Date:** Nov 21, 2025 - Nov 21, 2025  No Dealers

# Part 573 Safety Recall Report

25V701

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Dec 12, 2025 - Dec 12, 2025

Phased Recall

Date when VIN will be searchable: