



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V707

Manufacturer Name: Forest River, Inc.

Submission Date: Oct 17, 2025

NHTSA Recall No.: 25V707

Manufacturer Recall No.: 51-1991

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 23

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 FOREST RIVER STEALTH EVO

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Oct 08, 2024 - Mar 20, 2025

Number of potentially involved: 7

Descriptive Information:

All vehicles equipped with a 235/75/15LRD and a tire pressure of 80 PSI in the system are included.

Vehicle 2: 2025-2026 FOREST RIVER WILDWOOD

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Oct 03, 2024 - Aug 27, 2025

Number of potentially involved: 7

Descriptive Information:

All vehicles equipped with a 235/75/15LRD and a tire pressure of 80 PSI in the system are included.

Vehicle 3: 2026-2026 FOREST RIVER SALEM

Product Category: Trailers

Part 573 Safety Recall Report

25V707

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Jan 27, 2025 - Jun 18, 2025

Number of potentially involved: 1

Descriptive Information:

All vehicles equipped with a 235/75/15LRD and a tire pressure of 80 PSI in the system are included.

Vehicle 4: 2025-2025 FOREST RIVER SALEM

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Jan 27, 2025 - Jun 18, 2025

Number of potentially involved: 2

Descriptive Information:

All vehicles equipped with a 235/75/15LRD and a tire pressure of 80 PSI in the system are included.

Vehicle 5: 2025-2025 FOREST RIVER RPOD

Product Category:

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Feb 25, 2025 - Mar 14, 2025

Number of potentially involved: 6

Descriptive Information:

All vehicles equipped with a 235/75/15LRD and a tire pressure of 80 PSI in the system are included.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Due to a clerical error, incorrect tire PSI was entered for these units. The error is associated with an optional tire and wheel package for these trailers.

FMVSS1:

Part 573 Safety Recall Report**25V707****FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

Excessive tire pressure can lead to tire failure and increase risk of a crash.

Description of the cause:

Clerical error when entering the tire information for these optional tires into the system that generates the federal placard

Identification of any warning that can occur:

None

Component Manufacturer**Tier of Supplier:****Supplier Type:****Name:****Address:****Country:****Involved Components**

Component Name 1: FEDERAL PLACARD

Component Description: FEDERAL PLACARD

Component Part Number: N/A

Chronology

On 10/13/2025, Forest River received an email stating a dealer had complained that the fed tag on a single trailer had the incorrect tire inflation information.

On 10/16/2025, Upon researching it was found that a clerical error on a tire option had caused some vehicles to have incorrect tire inflation. A companywide search was done to find any vehicle built with the incorrect tire information.

On 10/17/2025, Forest Rivers Corporate Recall Committee voted to recall.

Part 573 Safety Recall Report**25V707**

Related NHTSA Recall Number:

Description of Remedy**Remedy Type:**

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace the Federal Placards.

What is the Forest River Customer Service Phone Number?
Salem, Wildwood and Stealth EVO (503) 831-5410
RPOD (574) 642-3112

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

RPOD West Coast Salem, Wildwood, and Sealth EVO
2780 College Ave 1429 SouthEast Uglow
Goshen, IN 46528 Dallas, OR 97338

How remedy component differs from recalled component:

Affected Component – Federal Placard
Replacement Component – Federal Placard

The Federal Placard will now have the correct tire PSI on it.

Identify how/when recall condition was corrected in production:

The week of 10/17/2025 the tire PSI information was corrected in the system.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to

Part 573 Safety Recall Report**25V707**

our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Nov 26, 2025 - Nov 26, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Nov 26, 2025 - Nov 26, 2025 Phased Recall

Date when VIN will be searchable: