



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

# Part 573 Safety Recall Report

## 25V750

**Manufacturer Name:** Par Nado inc

**Submission Date:** Feb 26, 2026

**NHTSA Recall No.:** 25V750

**Manufacturer Recall No.:** 2025-001

### Manufacturer Information

### Population

**Manufacturer Name:** Par Nado inc

**Address:** 821 du Parc  
St-Frederic Foreign States, G0N 1P0

**Total number of potentially involved:** 145

**Estimated percentage with defect:** 5.4%

### Vehicle Information

**Vehicle 1:** 2019-2020 Alto F1743

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jan 01, 2018 - Dec 20, 2019

**Number of potentially involved:** 75

**Descriptive Information:**

The vehicles included in the population are all equipped with the Dometic PI8022 2-burner LPG cooktop which in these models has had incidents of a leak on the tube connecting the regulator to the burners.

**Vehicle 2:** 2019-2020 Alto F2114

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Jan 01, 2018 - Dec 20, 2019

**Number of potentially involved:** 70

**Descriptive Information:**

The vehicles included in the population are all equipped with the Dometic PI8022 2-burner LPG cooktop which in these models has had incidents of a leak on the tube connecting the regulator to the burners.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

The aluminum supply tube of the Dometic cooktop, which connects the propane regulator valve to the burners, may crack.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

In such circumstances, a propane leak could occur, resulting in a fire and/or explosion, when starting the burners and/or in the presence of heat, sparks, or flames, which could cause bodily injury and property damage.

**Description of the cause:**

It appears that the supply line related to the cooktop, which connects the propane regulator to the burner supply valves, may crack as a result of excessive vibrations or shocks during transport.

**Identification of any warning that can occur:**

The owner and/or user may possibly hear a louder than normal hissing sound or smell propane odor. The flame height may also seem lower than normal. In addition, the control knob of the cooktop may fell loose and/or be difficult to operate.

# Part 573 Safety Recall Report

# 25V750

**Tier of Supplier:** Tier 1  
**Supplier Type:** OEM  
**Name:** Dometic Corporation  
**Address:** 5155 Verdant Drive  
 Elkhart IN, 46516  
**Country:** United States

## Involved Components

**Component Name 1:** Dometic PI8022 cooktop  
**Component Description:** 2-burner LPG cooktop  
**Component Part Number:** PI8022

## Chronology

2024/06/07 Safari Condo was informed by an insurer of an incident involving a recreational vehicle, following a fire that reportedly occurred under the Dometic cooktop.

2025/07/15 Safari Condo is informed by a customer of a possible gas leak at the supply line located under the Dometic cooktop in his vehicle.

2025/07/17 Safari Condo is informed by Transport Canada of a similar case of gas leak detected in the supply line located under the Dometic cooktop of a customer's vehicle.

2025/07/30 Safari Condo, in conjunction with Transport Canada, is inspecting the customer's vehicle. It appears, at a preliminary stage, that the aluminum pipe connecting the propane regulator valve to the burners of Dometic cooktops is cracked.

2025/08/26 Transport Canada opens an investigation into the problem of cracked pipes connecting the propane regulator valve to the burners of Dometic cooktops.

2025/09/04 Safari Condo informs its cooktop supplier, Dometic, of the problem related to the cracking of the propane supply lines of its products.

2025/09/26 Transport Canada sends a request for information to Safari Condo and informs them that they have traced twelve (12) incidents that are similar and the same model.

2025/10/14 Despite numerous discussions, Dometic has not proposed any measures to address the problem with the PI8022 cooktops.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Repair, Replace, Inspect

**Consumer Advisories:**  Do Not Drive  Park Outside

### Description of remedy program:

To remedy the situation, Safari Condo will ensure that a support bracket kit is provided and installed on the supply line by a technician certified to work on propane appliances. The cooktop will also be inspected as part of this recall to verify the presence of defects that could affect its proper operation. If applicable, the cooktop will be replaced at Safari Condo's expense. This recall may be carried out at a Safari Condo service center, at a Safari Condo product dealer, or at an RV dealer located near the customer's residence, provided that certified propane gas appliance technicians are available.

### How remedy component differs from recalled component:

The current installation did not have a support bracket for the supply line.

### Identify how/when recall condition was corrected in production:

The cooktop is no longer installed since the end of year 2019.  
 As a prevention, the support bracket for the supply line to the cooktop has been added to all units in production from February 16 2026.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

# Part 573 Safety Recall Report

## 25V750

Safari Condo and its teams are actively working to implement a permanent and safe solution. Safari Condo remains in communication with Dometic to ensure its collaboration and involvement in developing a corrective measure to address the safety defect affecting its product. Therefore the first recall communication will advise customers to stop using the potentially defective component and turn off the LPG supply.

Once a corrective measure has been established, a second communication will be sent advising on the final correction to address to potential defect.

It has been determined by Safari Condo that it will be faster to work with an expert to evaluate the remedy it proposes to implement in order to validate it is solid and secure. Once this is confirmed Safari Condo expects to be able to send Remedy Owner Notification letters starting February 26th.

**Planned Dealer Notification Date:** Nov 17, 2025 - Nov 17, 2025  No Dealers

**Planned Interim Owner Notification Date:** Nov 24, 2025 - Nov 28, 2025  No Owners

**Planned Remedy Owner Notification Date:** Feb 26, 2026 - Mar 05, 2026  Phased Recall

**Date when VIN will be searchable:**