



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V813

Manufacturer Name: Foretravel, Inc.

Submission Date: Nov 24, 2025

NHTSA Recall No.: 25V813

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: Foretravel, Inc.

Address: 1221 N.W. Stallings Drive
Nacogdoches TX, 75964

Total number of potentially involved: 7

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2020-2022 Foretravel Realm

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Oct 14, 2019 - Oct 08, 2021

Number of potentially involved: 4

Descriptive Information:

Villa International notified Foretravel Motor coach on 11/17/25

Vehicle 2: 2022-2022 Foretravel Realm 450

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Sep 10, 2021 - Oct 11, 2021

Number of potentially involved: 3

Descriptive Information:

Villa International notified Foretravel Motor coach on 11/17/25

Defect / Noncompliance Description

Description of the defect or noncompliance:

Part 573 Safety Recall Report

25V813

The pedestal incorrectly welded.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The pedestal incorrectly welded could fail in the event of a crash increasing the risk of injury.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Villa International

Address: 13760 Midway Street, Cerritos, CA. 90703
4733 Eastland Drive, Elkhart, IN. 46516
Cerritos CA, 90703

Country: United States

Involved Components

Component Name 1: Seat Pedestal

Component Description: Rotating seat base

Component Part Number: 400004

Chronology

On November 17, 2025 Villa International informed Foretravel Motorcoach they had determined that certain Foretravel motor homes equipped with Villa driver and passenger seating fail to conform to Federal Motor Vehicle Safety Standard NO. 207, "seating systems"

The Villa seats affected were fabricated and delivered to Foretravel Motorcoach on or around July 27,2021 through August 18,2021. These seats were installed in Foretravel coaches numbered 7123,

Part 573 Safety Recall Report

25V813

7124, 7125,9082, 9128, 9130, 9132.

On November 21,2025 Foretravel Motorcoach decided to instigate a Safety Recall on the involved vehicles above.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The recall remedy is to inspect for the incorrect pedestal weld of the can to the mounting plate among the vehicles determined to be affected. If the vehicle inspection reveals that a pedestal does have an improper weld, then the pedestal is required to be replaced for that seat.

How remedy component differs from recalled component:

Can to base is completely welded and not just tacked welded.

Identify how/when recall condition was corrected in production:

Foretravel uses a different seat and base assembly on production.

Reimbursement Plan

Description of reimbursement program:

The necessary time to inspect for the defective pedestal would be less than 5 minutes. Replacement of the pedestal will take approximately one hour labor.

Period of reimbursement:

Costs to be reimbursed:

One hour labor

Address for reimbursement claims:

1221 NW Stallings Dr,
811 NW Stallings Dr.
Nacogdoches TX, 75964

Recall Schedule

Part 573 Safety Recall Report**25V813****Description of recall schedule:****Planned Dealer Notification Date:** Nov 24, 2025 - Jan 24, 2026 No Dealers**Planned Interim Owner Notification Date:** No Owners**Planned Remedy Owner Notification Date:** Dec 02, 2025 - Feb 02, 2026 Phased Recall**Date when VIN will be searchable:**