



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V845

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Dec 09, 2025

NHTSA Recall No.: 25V845

Manufacturer Recall No.: D4C

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 313

Estimated percentage with defect: 1.3%

Vehicle Information

Vehicle 1: 2024-2024 ALFA ROMEO GIULIA

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Feb 02, 2024 - Dec 03, 2024

Number of potentially involved: 313

Descriptive Information:

Some 2024 Alfa Romeo Giulia Quadrifoglio ("QV") vehicles may have been built with a misrouted headlamp wire harness that may become damaged.

The suspect period began on February 2, 2024, when the first vehicle with a misrouted wire harness was produced, and ended on December 3, 2024, when vehicles with the misrouted wire harness were no longer being produced. Vehicle manufacturing records were used to determine the suspect population.

Similar vehicles not included in this recall were built before or after the suspect period.

The total affected vehicles for this model is 313.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Federal Motor Vehicle Safety Standard ("FMVSS") 571.108 S6.1.1 specifies the number of lamps and/or reflective devices for these suspect vehicles and their conformance to the performance requirements of this standard. The damaged harness may cause the headlamps not to function.

Part 573 Safety Recall Report

25V845

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A nonfunctional headlamp can reduce forward visibility which can cause a vehicle crash without prior warning.

Description of the cause:

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: SEWS - CABIND S.P.A.

Address: Corso Pastrengo, 40
Collegno (TO) Foreign States, 10093

Country: Italy

Involved Components

Component Name 1: Wire Harness

Component Description: Wire Harness Assembly

Component Part Number: 68717932AA / 68717907AA

Chronology

- On September 4, 2025, Stellantis Europe Control Tower organization was notified of a potential build issue resulting in a loss of headlamp functionality related to the wire harness routing in some Alfa Romeo Giulia QV vehicles.
- From September 2025, through November 2025, Stellantis Europe Control Tower met with Stellantis Europe Engineering and Manufacturing to review the issue, understand all potential failure modes, and to determine the suspect population.

Part 573 Safety Recall Report

25V845

- On November 26, 2025, Stellantis Europe Control Tower organization recognized that a build issue existed on certain vehicles related to the headlamp wire harness potentially resulting in a noncompliance with FMVSS No 108.
- On December 02, 2025, Stellantis Europe S.p.A determined, through the Vehicle Regulations Committee, that a noncompliance to a Federal Motor Vehicle Safety Standard No. 108 potentially exists in certain vehicles.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace, Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

FCA US will conduct a voluntary safety recall to inspect the wheel arch liner, and replace if necessary, and inspect the wire harness and re-route and/or repair if necessary.

How remedy component differs from recalled component:

This recall is not related to a part defect, but rather an assembly issue. The remedy will be to inspect the wheel arch liner, and replace if necessary, and inspect the wire harness and re-route and/or repair if necessary.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

**12/09/2025: FCA US will notify dealers on or about 12/16/2025 and begin notifying owners on or about 01/28/2026.

Planned Dealer Notification Date: Dec 16, 2025 - Dec 16, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Part 573 Safety Recall Report

25V845

Planned Remedy Owner Notification Date: Jan 28, 2026 - Jan 28, 2026 Phased Recall

Date when VIN will be searchable: Dec 16, 2025