



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V903

Manufacturer Name: Lamborghini (Automobili Lamborghini)

Submission Date: Dec 21, 2025

NHTSA Recall No.: 25V903

Manufacturer Recall No.: L636-R.01.26

Manufacturer Information

Population

Manufacturer Name: Lamborghini (Automobili Lamborghini)
Address: Via Modena 12
Sant'Agata Bolognese (BO)
40019 - Italy Foreign
States, 99999

Total number of potentially involved: 10,554
Estimated percentage with defect: 0.7%

Vehicle Information

Vehicle 1: 2019-2024 LAMBORGHINI URUS

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Jul 30, 2018 - Jan 26, 2025

Number of potentially involved: 10,554

Descriptive Information:

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Defect / Noncompliance Description

Description of the defect or noncompliance:

In certain situations, a software issue may prevent the rearview camera image from displaying.

FMVSS1: 111 - Rear visibility

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of a

Part 573 Safety Recall Report

25V903

crash.

Description of the cause:

Electrical noise, diminished shielding integrity, and timing may adversely affect rearview camera operation.

Identification of any warning that can occur:

If this occurs, the driver will notice the rearview camera image is not displayed. Owners who may experience this issue are advised to use extra caution when reversing, and they should contact an authorized Lamborghini dealer without delay to have the vehicle diagnosed.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Automobili Lamborghini S.p.A.

Address: Via Modena, 12
Sant'Agata Bolognese Foreign States, I-40019

Country: Italy

Involved Components

Component Name 1: Software for the control unit of driver assistance

Component Description: Software for the control unit of driver assistance systems

Component Part Number: n/a

Chronology

April 2025: Lamborghini was informed by one of the Volkswagen Group sister brands about an ongoing analysis of an issue that could prevent the rearview camera image from displaying in the infotainment system commonly used in some vehicle models across the Brands.

From May 2025 to October 2025: Lamborghini started its own investigation of field claims and vehicle characteristics in order to access involvement with the topic, even though the root cause, failure mechanism and consequences had not been fully understood.

October - December 2025: The technical analysis confirmed that increased signal noise between the control unit and the cameras can cause corrupted register data, which may lead to the failure of individual cameras within the Top View system. Additionally, measurements at coaxial cables of the field revealed an increased shielding resistance, and with that, reduced protection from electromagnetic interference, potentially caused by variations at crimp connections. This ultimately can result in camera failures within the Top View System.

Part 573 Safety Recall Report

25V903

December 15, 2025: The Lamborghini Product Safety Committee determined that the issue constitutes a noncompliance in the United States and decided a noncompliance recall.

Date of determination: December 15, 2025

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Remedial action is presently being developed and will be advised in due course. The analysis determined that the primary issue was software that lacked sufficient robustness. Even minor signal noise can cause register data corruption, potentially leading to the failure of one or more cameras within the Top View System, including the rearview camera. To address this, a more robust software solution that is more resistant to the signal noise is being developed to prevent such failures. This software will be installed on the affected vehicles.

How remedy component differs from recalled component:

The software solution can perform a self-healing process of the cameras during the driving cycle, if necessary, thereby preventing the failure. This self-healing process typically occurs quickly and in the background, so it is generally not noticeable to the customer unless the Top View system is active on the MMI.

Identify how/when recall condition was corrected in production:

The current production has a different technical solution from the vehicles included in this recall, with different application and routing due to a repositioning of the rearview camera on the new model year car layout.

Reimbursement Plan

Description of reimbursement program:

Any vehicles under warranty will be covered under Lamborghini's new vehicle warranty program. Customers who have paid for a repair of this defect out of warranty will be reimbursed by Lamborghini's reimbursement plan. A reimbursement plan will be offered under this recall. Owners will be instructed to contact their authorized Lamborghini dealership which will be able to submit a claim on customer's behalf to Automobili Lamborghini America LLC.

Period of reimbursement:

Expenses for repairs performed more than 10 days after the date of the last owner notification letter sent by Lamborghini are not eligible for reimbursement.

Costs to be reimbursed:

Part 573 Safety Recall Report

25V903

Expenses paid to repair facilities outside of the Lamborghini official network will be considered; however, the repair procedure must meet Lamborghini standards.

The authorized Lamborghini dealer will request a copy of the owner notification letter, as well as the previously paid invoice. The vehicle will be inspected before a reimbursement claim can be accepted.

Only a repair that is the subject of this recall is reimbursable. Consequential expenses such as towing, rental, accommodations, damage repairs, etc will not be reimbursed.

Repair labor, taxes and hazardous waste disposal, when previously paid, are eligible for reimbursement.

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Customers will be notified by registered mail and customer app while dealers through Lamborghini dealer portal.

Planned Dealer Notification Date: Jan 29, 2026 - Jan 29, 2026 No Dealers

Planned Interim Owner Notification Date: Feb 09, 2026 - Feb 16, 2026 No Owners

Planned Remedy Owner Notification Date: Phased Recall

Date when VIN will be searchable: