

**Daimler Truck  
North America LLC**

Daimler Truck North America LLC  
Warranty Campaigns Department  
P.O. Box 4090  
Portland, OR 97208-4090  
800.547.0712 Phone

**DATE:** 02/14/2025

**TO:** My Communication

**SUBJECT:** **SAFETY RECALL NOTICE – STOP DELIVERY:** F1016

On **January 28, 2025**, Daimler Truck North America (DTNA) filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) and/or a Defect Information Notice (DIN) with Transport Canada (TC) informing the agencies of our intent to conduct a voluntary safety recall.

It is a violation of Federal law for a dealer or distributor to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. **Some of the vehicles subject to this "Stop Delivery Notice" may be in your *new* vehicle inventory.** Until further instructions are available, ***new* vehicles subject to this "Stop Delivery Notice" must be held and not be delivered to customers.**

DTNA strongly recommends that dealers and distributors remedy Recalls before selling used vehicles. For any used vehicle with an open recall not remedied before sale, DTNA requires that the dealer or distributor notify prospective buyers of the open recall.

Please ensure that registration information on vehicles subject to this recall is up to date to facilitate accurate owner notification.

**Affected Vehicles in F1016:**

Make	Model	Model Yr. Start	Model Yr. End	Prod. Start Date	Prod. End Date
Freightliner Custom Chassis	XBS RV Chassis	2024	2024	January 2, 2024	January 8, 2024
Freightliner Custom Chassis	XCM RV Chassis	2022	2024	March 2, 2022	January 6, 2024
Freightliner Custom Chassis	XCR RV Chassis	2022	2025	April 13, 2022	January 16, 2024
Freightliner Custom Chassis	XCS RV Chassis	2024	2025	October 11, 2023	January 11, 2024

**Problem:** The remote fuel filter hoses installed on the subject engines can become separated from the fuel fitting resulting in fuel leaks and lack of fuel supply to the engine. A fuel hose that becomes disconnected will result in an engine stall, increasing the risk of a crash. A fuel leak in the presence of an ignition source may increase the risk of a fire. Persons operating in or around the vehicle may see smoke or other visible signs of a fuel leak or smell diesel fuel.”

**Solution:** The remedy is to replace the subject fuel hoses with hoses having improved connector crimps.

**Owner Notification Mailing Schedule:** 03/11/2025