


Recall 25V-042 (Flat Rate 900007) CAN 2025-038
Model G MPPT Solar Controller

It has been decided that the vehicles in the recall population were assembled with MPPT Solar Controllers that have a defective internal component. The remedy is to replace the suspect controllers with the latest version controller, which has been modified to prevent this failure mode. Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.

This recall affects a total of 1794 vehicles.

Model G VIN Range



NOTICE

**IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY
NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION
UNTIL THE VEHICLE HAS BEEN REPAIRED.**