

**Reference Number: 202506160004**

GENERAL MOTORS

DCS7247

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 16, 2025

Subject: REVISION: N242490120-04 - Safety Recall

Chrome Grille Deflector May Detach

Revised Parts Table and Service Procedure sections

Models: 2022 GMC Sierra 1500

This bulletin has been revised to update the parts table and service procedure sections. Please discard all previous copies of bulletin N242490120.

**If you are using an equivalent adhesive to the Lord Fusor® 133, ensure that is fast setting and it MUST be compatible with ABS plastics.**

**DO NOT reinstall the Deflector until after allowing the epoxy to dry and cure for a MINIMUM OF 1 hour or per the manufacturer's instructions if using an equivalent adhesive.**

END OF MESSAGE