

AIRSTREAM®

1001 W. Pike St., Jackson Center, OH 45334

IMPORTANT SAFETY RECALL

Airstream Classic Travel Trailer

NHTSA 25V143 / Transport Canada 2025-116

Date: 3/27/2025

TO: Airstream Dealer

PROBLEM:

It has come to our attention that in certain model year **2021-2025 Classic travel trailers**, sofas containing footrest switches without a stop limit component were produced with underrated wires for the application. If the switch is depressed for an extended period, the wires could heat up, resulting in a fire, increasing the risk of personal injury and/or property damage.

RANGE OF VEHICLES INVOLVED:

Model Year 21-25 33' Classic built between: March 5, 2021 – February 24, 2025

Serial Number Range: 556314 – 575508

Model Year 24-25 30' Classic built between: July 21, 2023 – February 25, 2025

Serial Number Range: 568592 - 575863

Model Year 25 28' Classic built between: December 19, 2024 – January 30, 2025

Serial Number Range: 574267 - 575477

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the owner's letter is included for your review. An owner may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the repair advised and send a warranty claim referencing this recall number for reimbursement. The time allowed for repair is **1.00 hrs.**

SERVICE ACTION:

The remedy is to install reverse relays on the sofa switch assemblies of the affected units, according to the instructions provided. Please use operation code **TTSBR8939100** when submitting a claim for warranty reimbursement.

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

encl. – Owners Letter, Repair Procedure



Rick March

General Manager of Airstream Customer Service Group

Re: NHTSA Recall No. 25V-143

Transport Canada 2025-116