

ASA2 Recall Campaign - Replace front seat cushion (passenger side)

ASA2 Recall Campaign - Replace front seat cushion (passenger side)

ID Number	ASA2
Affected Model(s)	Taycan (Y1A/Y1B/Y1C)
Affected Model Year(s)	2022 - 2023
VIN List	Attached below
Number of Affected vehicles	9,684
Issue Description	Due to a manufacturing error, the occupant classification system for automatic airbag activation/deactivation in the front passenger seat can trigger a fail-safe mode which deactivates the airbag in the front passenger seat.
What should Porsche Centers do?	The subject vehicles will be reprogrammed and have the front passenger seat occupancy cushion replaced. The remedy is not yet available at this time.
What will Porsche do?	The subject vehicles will be reprogrammed and have the front passenger seat occupancy cushion replaced. The remedy is not yet available at this time.
Technical Information	To be posted at a later date.
Parts Status	Status 7 - No parts are available
Customer Letter	To be posted at a later date.
Customer Reactive Statement	The safety of our customers and quality of our cars are of paramount importance. We identified a potential electrical connection issue in the front passenger seat cushion installed in certain 2022 and 2023 model year Taycan variants. If this issue occurs, an airbag warning lamp illuminates in the dashboard. Affected customers will be notified and their vehicles will be updated with a new seat cushion at a Porsche Center, free of charge.