

✕ Fwd: RECALL - TPS Shipment for Affected Units



MESSAGE HEADERS

MESSAGE

THREAD

[Redacted] to [Redacted] and 2 others

Tuesday, April 15, 2025, 5:01 PM (125 days ago)

Aloha,

We've coordinated with Yamaha Motor Corporation, U.S.A. to ship a new Throttle Position Sensor (TPS, Part #90891-30169-00) directly to your dealership for each affected unit sold from your inventory.

The TPS units will appear as charges on your parts bill from YMUS. We will fully reimburse these charges.

You can track the order status in the Yamaha Dealer System with the Order #211256125.

USPS states the TPS units have been delivered, "Front Desk/Reception/Mail Room HONOLULU, HI 96819 April 14, 2025, 9:40 am."


For sold or demo units, please make sure the ECU reprogramming and TPS replacement are completed as detailed in the bulletin.

For unsold units, only ECU reprogramming is required. Thank you so much for your quick attention to this safety recall and your continued partnership.

Mahalo!

[Redacted]
Principal
Yamaha of Hawaii

Email: [Redacted]
Web: www.yamahaofhawaii.com



Yamaha Bulletin-YMC Recall MRM2501.pdf (987 KB)

[Download](#) [View VirusTotal report](#)

SHA-256: ebb29064690810a8cf8d488c4ca9f394813ac750ce7f7503c8c7a4937e24fcc8