



P/A Code: [REDACTED]

MAY 2025

[REDACTED]
[REDACTED]
[REDACTED]

ATTN: SERVICE MANAGER

Subject: VEHICLE DELIVER HOLD- Compliance Recall 25C12

Compliance Recall 25C12
Certain 2025 Model Year F-150
Missing Dashboard Air Bag Warning Label

REASON FOR PROGRAM:

All of the affected vehicles may be missing the dashboard air bag warning label and do not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) 208 S4.5.1(e) Occupant Crash Protection / Labeling and Owners Guide Information.

NOTE: The information on the missing label is also included on the sun visor label and in the Owner's guide if customers have questions.

SERVICE ACTION

UNSOLD Vehicles: Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to:

- Install provided air bag warning labels per Technical Instruction detail.
- Can be done in service drive.
- Respective dealers will be mailed labels for the inventory on hand plus extra as needed.



P/A Code: [REDACTED]

MAY 2025

Records indicate the following stock units need warning label

Number of VINs: 4

		Model Year/Vehicle	Part #
1.	[REDACTED]	2025 F-150 Ford Truck	[REDACTED]
2.	[REDACTED]	2025 F-150 Ford Truck	[REDACTED]
3.	[REDACTED]	2025 F-150 Ford Truck	[REDACTED]
4.	[REDACTED]	2025 F-150 Ford Truck	[REDACTED]