

Reference Number: 202506050006

GENERAL MOTORS

DCS7242

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 5, 2025

Subject: REVISION & UPDATE: N252494000-04 - Safety Recall

L87 Engine Loss of Propulsion

Additional VINs Moved to Open/Revised Correction Statement,
Service Procedure and Parts Table

Models: 2021-2024 Cadillac Escalade
2021-2024 Cadillac Escalade ESV
2021-2024 Chevrolet Silverado 1500
2021-2024 Chevrolet Suburban
2021-2024 Chevrolet Tahoe
2021-2024 GMC Sierra 1500
2021-2024 GMC Yukon
2021-2024 GMC Yukon XL

To: All General Motors Dealers

This bulletin is being revised to update the correction statement, step 31 in the service procedure and adding the 55 gallon drum part number. Please discard all previous copies of bulletin N252494000.

Additional vehicles have been moved to 'Open' status in IVH. Please verify a VIN's involvement in this field action by checking in IVH prior to doing any repairs.

For dealers with involved vehicles, a listing has been prepared and will be available through GM Global Connect Maxis Field Action Reports or GWM Field Action Batch Search Report. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the PROMPT COMPLETION of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

END OF MESSAGE