

Content Id: 17625

GENERAL MOTORS

DCS7421

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 30, 2026

Subject: REVISION: N252494000-11 – Safety Recall
L87 Engine Loss of Propulsion
Revised Service Procedure **Updated Information*

Models: 2021-2024 Cadillac Escalade
2021-2024 Cadillac Escalade ESV
2021-2024 Chevrolet Silverado 1500
2021-2024 Chevrolet Suburban
2021-2024 Chevrolet Tahoe
2021-2024 GMC Sierra 1500
2021-2024 GMC Yukon
2021-2024 GMC Yukon XL

This bulletin is being revised to update the L87 Picoscope test in the service procedure. Please discard all previous copies of bulletin N252494000.

**Updated Information - IMPORTANT: The procedure for the L87 Picoscope test has been updated to remove manual Picoscope data collection and entry. Please review the service procedure in its entirety before proceeding. DO NOT manually attempt to start the GM NVH software. GM NVH SOFTWARE CANNOT be running at the same time as SPS.*

This update will be pushed to Techline Connect (TLC) on February 2, 2026. When TLC is opened, it will automatically download the new software.

END OF MESSAGE