

# IMPORTANT SAFETY RECALL



## NHTSA Recall 25V-286 (CAN 2025-238)

### Claim Preparation & Inspection/Repair Instructions

Please complete a warranty pre-authorization request using the following codes & labor times:

#### **Labor:**

Flat Rate Code: **900008**  
Fault Code: **Supplier Component Failure - Loose**  
Time Allowed: **0.3 hrs**

**Parts:** *\*Note: Parts are only available to order by VIN- NO STOCK ORDERS\**

Brinkley Model	Floor Plan	VIN Range	BRV Kit Number	Defective MORryde Bracket	MORryde Replacement Kit Number
Model G	All	0919-2238	K117579	STP56-015	STP54-080
Model Z	3400	3269-3374 3493-3856		STP56-015	STP54-080
Model Z	3400	3375 3857-7218	K117580	STP56-038	STP54-086

#### **Pre-Authorization:**

No prior inspection is required. All Brinkley RV dealer recalls will require preauthorization approval prior to claim creation. Promptly file preauthorization through our dealer portal using the information above to confirm the correct flat rate is applied.

#### **Claim Filing:**

When repair is complete, promptly file a claim through our dealer portal. ***Required photo (1): Photo of new bracket installed, with the correct mounting screw placement according to the Work Instructions.*** If you have any questions, please call our Customer Care Team at (574)501-4280.