

ASA6 Stop Delivery / Recall Campaign - Check the air suspension strut on the front axle and rework if necessary

ASA6 Stop Delivery / Recall Campaign - Check the air suspension strut on the front axle and rework if necessary

Important Information

PORSCHE CENTERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. PORSCHE CENTERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Any vehicles delivered to customers before this announcement may be released from Stop Delivery by sending a PRMS Warranty / Campaigns Ticket to PCNA_Warranty_Support in PRMS. The ticket must have proper documentation of the sale / delivery.

ID Number	ASA6
Affected Model(s)	Taycan (Y1A, Y1B, Y1C) Panamera (YAA, YAB)
Affected Model Year(s)	2024-2025
VIN List	Attached below
Number of Affected Vehicles	284 49 Stop Delivery
Issue Description	There is a potential issue with the retaining ring on the front air suspension.
What should Porsche Centers do?	Please do not deliver any affected vehicles at this time. The remedy is now available.
What will Porsche do?	Vehicles will have the remedy carried out as soon as available.
Technical Information	ASA6
Parts Status	Status 0 - No parts required.

ASA6 Stop Delivery / Recall Campaign - Check the air suspension strut on the front axle and rework if necessary

Customer letter

To be posted at a later date.

Customer Reactive Statement

The safety of our customers and the quality of our cars are the top priorities at Porsche. Through regular and ongoing quality checks, a potential issue with the retaining ring on the front suspension strut of a small number of Taycan and Panamera vehicles was discovered. This is a precautionary step - no incidents have been reported as a result of this issue. Affected customers will be contacted and the remedy will be carried out at a Porsche Center of their choice free of charge.

Attachments

1. [VIN_List_Report_ASA6_2025-07-16_V3.xlsx](#)