

SAFETY RECALLS H552/N945 - PASSENGER AIRBAG REPLACEMENT

SAFETY RECALLS - H533/N945 - PASSENGER AIRBAG REPLACEMENT	
AFFECTED MODELS	21-24MY E-PACE 21-25MY Range Rover Evoque
VOLUME AFFECTED	H552 – 1436 US 95 CAN N945 – 20999 US 3115 CAN
REPAIR	A concern has been identified on certain vehicles were, during a passenger airbag deployment, the airbag may tear as a result of improper folding of the airbag during the airbag assembly process. A replacement passenger airbag will be required.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Vehicle quarantine notices were published on July 10th, 2025. Retailers were also notified by Recall Admin Bulletins N945 (July 18th, 2025) and H552 (July 16th, 2025.) Technical Q & A to be appended.
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Please refer to recall bulletin for instructions on used vehicles in retailer inventory. The service repair bulletins are pending supply of parts which are currently TBA but expected to have a lead time of several months. All affected VINs are flagged in the warranty portal and also in BBBS for those in retailer inventory.