

IMPORTANT SAFETY RECALL



FOREST RIVER

DEPARTMENT OF COMPLIANCE
VEHICLE SAFETY AND RECALL MANAGEMENT
PO Box 30
MIDDLEBURY, INDIANA 46540-9218

NHTSA RECALL: 25V486
FOREST RIVER ID: 51-1955
SERVICE CAMPAIGN: 001230

<<DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o Integrity
- o Safety
- o Quality
- o Customer Service

December 2025

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

–Forest River motorized and towable products are contained in this section–

Forest River has decided that a safety defect exists in certain 2025-2026 Forester FRC2551DSLEF, 2025-2026 Leprechaun LPC260DSF, LPC260MBF45, LPC260QBF8RB9 & LPC270QBF35, 2025-2026 Sunseeker SSC2550DSLEF & SSC2550DSLEFRB, 2025-2026, 2025–2026 Solera DSC27DSEF, Frelander FLC26DSF45, FLC26MBF45, FLC27QBC3500, FLC27QBF35 & FLC27QBF45, and 2025–2026 Entrada EAC2600DSF, EAC2700NSF & EAC2710NKF Class C Motorhome Recreational Vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River apologizes for any inconvenience this action may cause your dealership; however, safety, continued satisfaction, and our commitment to building great products are of the utmost importance to Forest River.

WHAT IS THE DEFECT?

The fuel line extension may have been inconsistent crimps at the barb fittings of its connectors which can cause the fittings to become loose and detach.

EVALUATION OF RISK:

If a fuel line detaches, this may allow fuel to openly spray. This condition may lead to fire and property damage.

SERVICE PROCEDURE:

THE REMEDY FOR THIS RECALL IS BEING ISSUED IN 2 PHASES – THIS IS THE PHASE TWO RELEASE. ALL REPAIRS ARE NOW AVAILABLE.

PHASE 1 - PARTS ARE NOW REDILY AVAILABLE WHICH CONTAIN 44” FUEL HOSES. THE FUEL HOSE(S) WILL NEED TO BE REPLACED AS PER THE REMEDY INSTRUCTIONS.

PHASE 2 – PARTS ARE NOW REDILY AVAILABLE WHICH CONTAIN 32” FUEL HOSES. THE FUEL HOSE(S) WILL NEED TO BE REPLACED AS PER THE REMEDY INSTRUCTIONS.

WHAT IS THE PART NUMBER OF THE REMEDY KIT?

F100231288 – 44” FUEL LINE (PHASE 1)

F100231286 – 32” FUEL LINE (PHASE 2)

PARTS AND RETURN:

Part return is required – please follow the instructions within the remedy instructions for part return.

DEALER REPAIR CODES:

PRIOR AUTHORIZATION IS REQUIRED

UNITED STATES	REPAIR CODE	DESCRIPTION	ALLOWABLE HOUR(S)
25V486	RC-039-01-00-004751	PERFORM REMEDY	1.0 HRS.

IMPORTANT SAFETY RECALL

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE	EMAIL
FORESTER AND SUNSEEKER	(574) 206-7600	motorizedservice@forestriverinc.com
LEPRECHAUN AND FREELANDER	(574) 825-8602	rross@forestriverinc.com
ENTRADA	(574) 264-6664	

The Recall shall be considered the utmost priority to remedy the 2025-2026 Forester FRC2551DSLEF, 2025-2026 Leprechaun LPC260DSF, LPC260MBF45, LPC260QBF8RB9 & LPC270QBF35, 2025-2026 Sunseeker SSC2550DSLEF & SSC2550DSLEFRB, 2025-2026, 2025–2026 Solera DSC27DSEF, Freelanders FLC26DSF45, FLC26MBF45, FLC27QBC3500, FLC27QBF35 & FLC27QBF45, and 2025–2026 Entrada EAC2600DSF, EAC2700NSF & EAC2710NKF Class C Motorhome in question. **The retail consumer shall not be charged** any amount of monies for remedy to their 2025-2026 Forester FRC2551DSLEF, 2025-2026 Leprechaun LPC260DSF, LPC260MBF45, LPC260QBF8RB9 & LPC270QBF35, 2025-2026 Sunseeker SSC2550DSLEF & SSC2550DSLEFRB, 2025-2026, 2025–2026 Solera DSC27DSEF, Freelanders FLC26DSF45, FLC26MBF45, FLC27QBC3500, FLC27QBF35 & FLC27QBF45, and 2025–2026 Entrada EAC2600DSF, EAC2700NSF & EAC2710NKF Class C Motorhome listed under this Recall.

If your dealership has already performed the remedy to 2025-2026 Forester FRC2551DSLEF, 2025-2026 Leprechaun LPC260DSF, LPC260MBF45, LPC260QBF8RB9 & LPC270QBF35, 2025-2026 Sunseeker SSC2550DSLEF & SSC2550DSLEFRB, 2025-2026, 2025–2026 Solera DSC27DSEF, Freelanders FLC26DSF45, FLC26MBF45, FLC27QBC3500, FLC27QBF35 & FLC27QBF45, and 2025–2026 Entrada EAC2600DSF, EAC2700NSF & EAC2710NKF Class C Motorhome, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s). If the remedy needs to be performed on an out of warranty 2025-2026 Forester FRC2551DSLEF, 2025-2026 Leprechaun LPC260DSF, LPC260MBF45, LPC260QBF8RB9 & LPC270QBF35, 2025-2026 Sunseeker SSC2550DSLEF & SSC2550DSLEFRB, 2025-2026, 2025–2026 Solera DSC27DSEF, Freelanders FLC26DSF45, FLC26MBF45, FLC27QBC3500, FLC27QBF35 & FLC27QBF45, and 2025–2026 Entrada EAC2600DSF, EAC2700NSF & EAC2710NKF Class C Motorhome in which the VIN falls under as stated in the identified VIN listing, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s).

Notice:

In no manner shall a Forest River Product Owner or Coachmen Product Owner be charged any fee(s) for scheduling, conduction or completion of the recall. Additionally, all dealership(s) that are Forest River and/or Coachmen dealership(s) are Federally Mandated to perform the recall once presented with this recall whether by the Owner or Dealership receipt of this letter, without denial of service to the Owner. Lastly, denial of a remedy for this recall is a Federal Violation punishable by law resulting substantial fines and/or civil penalties.

Federal Regulation requires that any lessor receiving this Recall must forward a copy of this notice to the lessee within ten days. If your dealership no longer owns this vehicle, please inform the Warranty Manager of the product listed above of the change of ownership.

Sincerely,
Forest River, Inc.
Office of Corporate Compliance