

[View this email in your browser](#)

IMPORTANT SAFETY RECALL



MODEL Z RECALL

Under Floor Wiring

8/4/25

Dear <dealer>

It has been decided that the vehicles in the recall population were assembled without the standard wire harnesses utilized by Brinkley RV. In place of the wiring harness, individual wires were ran in the recalled units. In certain circumstances, these individual wires may migrate below holding tanks, creating a pinch point between the tanks and underlying support members.

We are conducting a Recall Campaign to address this concern for all Model Z units within the following VIN ranges: [REDACTED].

NOTICE

IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION UNTIL THE VEHICLE HAS BEEN REPAIRED.

The remedy is to inspect, and if necessary, secure/repair under floor wiring.

Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.

See the Dealer Portal for further details and associated documentation:

1. Sample Retail Owner notification letter

2. Claim Prep & Filing instructions
3. Recall Field Work Instructions
4. NHTSA 573 Safety Recall Report
5. NHTSA Recall Acknowledgement Letter

Relevant information is also being communicated via our Dealer Portal. Retail customers are being contacted through traditional hard copy mailings and e-mail.

We apologize for any frustration or inconvenience that this situation causes.

Sincerely,

Brinkley Customer Care

Phone: (574) 501-4280

Email: CustomerCare@BrinkleyRV.com

Let's Get Social!



[Why Brinkley RV?](#) | [Model Z](#) | [Model G](#) | [BrinkleyRV.com](#)

Copyright © 2023 Brinkley RV, All rights reserved.

Want to change how you receive these emails?

You can [update your preferences](#) or [unsubscribe from this list](#).