

---

## D041ADM1 - Range Rover (L405) Front Suspension Knuckle Crack


---

From JLRNA Customer Service Publications <jlrna-customer-service-publications@jaguarlandrover.com>

Date Fri 2025-08-15 8:56 AM

To c1sbutz88v@jlrdemo.netlink.com <c1sbutz88v@jlrdemo.netlink.com>

Cc um-nsc-usa-lr-alerts <um-nsc-usa-lr-alerts@jaguarlandrover.com>

 1 attachment (227 KB)

D041ADM1.pdf;

### **TO: Land Rover Authorized Retailer Aftersales Personnel**

Please find attached the following Jaguar Land Rover Aftersales publication.

- **Administration Bulletin for Safety Recall D041 - Range Rover (L405) Front Suspension Knuckle Crack**

#### **Concern:**

A concern has been identified on certain 2016 model year Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm, which under extreme avoidance maneuver use conditions may compromise the vehicle's controllability and increase the risk of a crash.

**Volume:** 6,741 US

#### **Action:**

Please review the content in the attached administration bulletin and observe all instructions relating to unsold vehicles in retailer inventory. A bulletin with repair instructions will be published as soon as the necessary parts are available.

All affected vehicles are flagged in the warranty portal immediately.

**PLEASE DO NOT REPLY TO THIS EMAIL.**

**CUSTOMER SERVICE PUBLICATION**



CONFIDENTIALITY NOTICE: The email message including attachments is intended only for the person to whom it is addressed and may contain confidential information. Any unauthorised review, use, or disclosure is prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message.