

# Safety Recall 283: Seat Belt Buckle Assembly (No Remedy) – Dealer Notification

September 26, 2025

Document Topic	Date
• Remedy Not Available	09/26/2025



**IMPORTANT:** As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

To check vehicle specific recall applicability, access the “Vehicle Information” screen via GWMS.

## Recall Description

The subject vehicles are equipped with seat belt buckle assemblies in the front row and second row outer seating positions that may contain out-of-specification components manufactured by the supplier. These components can cause interference within the latch channel, potentially increasing friction, particularly under cold ambient temperatures. Improperly produced seat belt buckles, combined with slow insertion of the seat belt tongue plate, may prevent the seat belt buckle from fully latching. An inability to fasten the seat belt in an occupied seat could increase the risk of injury to occupant(s) during a crash.

## Applicable Vehicles (Certain)

- 2020-2025MY Palisade (LX2) produced from 04/10/2019 – 06/16/2025 and built by Hyundai Motor Company (“HMC”)

## Remedy Information

The recall remedy is currently under development, and additional information will be provided once it is made available by HDPR. Owners can continue driving these vehicles; however, Hyundai advises occupants to fasten the seat belt firmly into the buckle with quick and direct motion. Once buckled, pull on the belt to confirm the seat belt is fully secured.

Please note that **Warranty Extension 51D266** continues to be in effect. The repair procedure and associated parts that are covered by the warranty extension are still available to customers who experience any seat belt buckle concerns. Should a customer express concern with the seat belt buckle(s) in their vehicle, please follow the repair procedure outlined in the TSB.

**IMPORTANT:** The repair parts supporting Warranty Extension 51D266 repairs are not recall remedy parts and will not satisfy the open recall on any vehicle. Please ensure customers acknowledge this condition should the replacement of any seat belt buckle(s) be necessary. A return visit to the dealer will be required to address the recall once the remedy is made available.

## Additional Information

Warranty information will be updated once the remedy has been released by HdPR. Parts information, if applicable, will be provided once a remedy has been released by HDPR. Applicable training courses related to this recall, if applicable, will be provided once a remedy has been released.