

ASA9 Stop Delivery / Recall Campaign - Check the high-pressure pump connections and, if necessary, replace the high-pressure pumps including fuel lines

ASA9 Stop Delivery / Recall Campaign - Check the high-pressure pump connections and, if necessary, replace the high-pressure pumps including fuel lines

ID Number	ASA9
Affected Models	Panamera (YAA) Cayenne (9YA/ 9YB)
Affected Model Years	2024-2026
VIN List	Attached below
Number of Affected Vehicles	107
Issue Description	On the affected vehicles, it is possible that the screw connections of the high-pressure pumps were not carried out according to specifications due to an error in the production process.
What should Porsche Centers do?	Please arrange for the remedy to be carried out on affected vehicles as soon as the remedy is available. Do not delivery any vehicles in vehicle inventory prior to completing the remedy.
What will Porsche do?	Vehicles will have the remedy carried out as soon as available. The remedy is now available as of 10/17/25.
Technical Information	ASA9
Parts Status	Status 1 - Order as needed.
Customer letter	To be posted at a later date.
Customer Reactive Statement	To be posted at a later date.

ASA9 Stop Delivery / Recall Campaign - Check the high-pressure pump connections and, if necessary, replace the high-pressure pumps including fuel lines

Required parts

A failure **rate** of approx. **50%** is expected during the check.

The required parts for carrying out the campaign can be found in the respective Technical Information (TI), "Warranty Processing" section.

For the **check** on **Cayenne** vehicles, **no** additional parts are required.

For the **check** on **Panamera** vehicles, **standard parts** are required. These can be found in the Technical Information (warranty processing, **scope 5**).

The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Warranty processing

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Scope 1 to Scope 4:

- **Cayenne (9YA/9YB) - Checking the screw connections takes 98 TU (scope 1)**

Damage Code	ASA9 99 000
Repair Code	1/2
Labor time	98 - 728 TU

Scope 5 to Scope 11:

- **Panamera (YAA) - Checking the screw connections takes 306 TU (scope 5)**

Damage Code	ASA 99 000
Repair Code	1/2

ASA9 Stop Delivery / Recall Campaign - Check the high-pressure pump connections and, if necessary, replace the high-pressure pumps including fuel lines

Labor time

306 - 2,418 TU

Attachments

1. [VIN_List_Report_ASA9_2025-10-17_V3.xlsx](#)