

From: [noreply-bms-notifications](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW Recall 25V-xxx: Replace Starter - B58
Date: Thursday, September 25, 2025 12:24:21 PM

Publish Date: September 25, 2025
From: Technical Service
Expiration Date: October 9, 2025

DCSnet Message
Urgent

Subject: **BMW Recall 25V-xxx: Replace Starter - B58**

BMW AG is conducting a Voluntary Safety Recall (effective September 25, 2025) on certain Model Year 2019 - 2025 BMW vehicles that were produced between July 11, 2018, and February 11, 2025.

This safety recall involves the engine starter. In certain cases, the engine starter may not start the vehicle properly. These improper starting attempts could result in local overheating of the engine starter. If the starter overheats, locally, during these starting situations, the engine acoustic protection material can be ignited if contaminated. In rare cases, this could lead to a thermal event while driving or shortly after parking, if the vehicle had a starting event shortly before being parked.

The Recall Notice and FAQ have been attached for further information.

The bulletin will be updated when additional information becomes available.

Sincerely,

Technical Service

Attachments:

[B121325\[1758817334743\].pdf](#)

[B121325 Recall Notice\[1758817346349\].pdf](#)

[B121325_25V-xyz-Starter-6-cyl.-Engines-FAQ-\(25Sep2025\)](#)

[\[1758817356826\].pdf](#) [B121325\[1758817334743\].pdf](#)
[B121325 Recall Notice\[1758817346349\].pdf](#)
[B121325_25V-xyz-Starter-6-cyl.-Engines-FAQ-\(25Sep2025\)\[1758817356826\].pdf](#)

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), All Offering, All Region, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All
BMW SAV (Light Trucks) CC-All

Safety Recall
25V-xyz
Starter – 6-cyl. Engines
Model Year 2019-2025
BMW 3 Series, 7 Series, 8 Series
BMW X5, X6, X7
09/25/2025

Q1. Which BMW models in the US are potentially affected by this Safety Recall?

Certain Model Year 2019-2025 BMW 3 Series, 7 Series, 8 Series, X5 SAV, X6 SAV, and X7 SAV models, in the US are potentially affected.

Q2. What is the specific issue?

This safety recall involves the engine starter. In certain cases, the engine starter may not start the vehicle properly. These improper starting attempts could result in local overheating of the engine starter. If the starter overheats, locally, during these starting situations, the engine acoustic protection material can be ignited if contaminated. In rare cases, this could lead to a thermal event while driving or shortly after parking, if the vehicle had a starting event shortly before being parked.

Q2a. This sounds familiar. My vehicle was repaired under BMW Safety Recall 24V-576. Do I need to have it repaired again?

Yes. If you had the vehicle repaired under safety recall 24V-576, you need to have it repaired again.

Q3. Why are other models / vehicles not included in this Safety Recall?

This recall affects vehicle models with a specific engine starter and vehicle configuration from a specific supplier produced during a specific period of time.

Q4. Can I continue to drive my vehicle?

Yes. However, when you are notified by BMW of this Safety Recall that a remedy is available, please contact an authorized BMW center to schedule an appointment as soon as possible. For the latest updates to this Safety Recall, please visit bmwusa.com/recall. **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**

Q5. How did BMW become aware of the issue?

BMW became aware of the issue through its quality control procedures.

Q6. How will I be informed of this Safety Recall?

Owners of potentially affected vehicles will be notified via First Class mail advising them of this Safety Recall and to schedule an appointment with an authorized BMW center as soon as possible to have the remedy performed. To locate your nearest authorized BMW center, please visit bmwusa.com/dealer.

To ensure BMW has the most up-to-date contact and vehicle information, owners should register their vehicle at bmwusa.com/myBMW. Registration is free and will give them access to other information specific for their BMW vehicle. Alternatively, owners can visit bmwusa.com/recall and click on “**Manage recall notices and contact information**”.

Q7. How will my vehicle be remedied?

Potentially affected vehicles will have the starter replaced *for free*.

Q8. Do I have to wait for BMW to contact me to have the remedy performed?

Yes. BMW is currently in the process of ensuring that the necessary tools, parts, and procedures are available prior to contacting you to schedule an appointment with an authorized BMW center. For the latest updates to this Safety Recall, please visit bmwusa.com/recall.



SIB 12 13 25

RECALL 25V-XXX: REPLACE STARTER – B58

2025-09-25

MODEL

E-Series	Model Description	Production Date	Affected Engine Type
G05	X5 Sports Activity Vehicle	July 11, 2018 – July 29, 2020	B58C
G06	X6 Sports Activity Coupe	July 15, 2019 – July 29, 2020	B58C
G07	X7 Sports Activity Vehicle	October 30, 2018 – July 29, 2020	B58C
G12	7 Series Sedan	February 12, 2019 – June 13, 2022	B58C
G14	8 Series Convertible	February 18, 2019 – February 6, 2025	B58C
G15	8 Series Coupe	June 11, 2019 – February 11, 2025	B58C
G16	8 Series Gran Coupe	June 24, 2019 – February 10, 2025	B58C
G20	3 Series Sedan	February 21, 2019 – July 28, 2020	B58D

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of September 26, 2025, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective September 25, 2025) on certain Model Year 2019 - 2025 BMW vehicles that were produced between July 11, 2018, and February 11, 2025.

This safety recall involves the engine starter. In certain cases, the engine starter may not start the vehicle properly. These improper starting attempts could result in local overheating of the engine starter. If the starter overheats, locally, during these starting situations, the engine acoustic protection material can be ignited if contaminated. In rare cases, this could lead to a thermal event while driving or shortly after parking, if the vehicle had a starting event shortly before being parked.

The Recall Notice and FAQ have been attached for further information.

The bulletin will be updated when additional information becomes available.

Powered by [Froala Editor](#)

Supporting Materials

[picture_as_pdf B121325 Recall Notice.pdf](#)

[picture_as_pdf B121325_25V-xyz-Starter-6-cyl.-Engines-FAQ-\(25Sep2025\).pdf](#)

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 25V-xxx: Replace Starter – B58 – B12 13 25

BMW AG is conducting a Voluntary Safety Recall (effective September 25, 2025) on certain Model Year 2019 - 2025 BMW vehicles that were produced between July 11, 2018, and February 11, 2025.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.