

From: [noreply-bms-notifications](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW Recall 25V-xxx: Check Drivers Front Air Bag (PSDI-4)
Date: Friday, October 31, 2025 12:57:18 PM

Publish Date: October 31, 2025
From: Technical Service
Expiration Date: November 14, 2025

DCSnet Message
Urgent

Subject: **BMW Recall 25V-xxx: Check Drivers Front Air Bag (PSDI-4)**

BMW AG is conducting a Voluntary Safety Recall (effective October 31, 2025) on certain Model Year 2000 - 2001 BMW vehicles that were produced between February 19, 1999, and March 31, 2000.

This recall campaign involves a sport, or M-sport, steering wheel equipped with the Takata PSDI-4 inflator. Some customers may have switched their original steering wheel which was not affected, to the sport, or M-sport, steering wheel which may include a potentially affected inflator.

The Recall Notice and FAQ have been attached for further information.

The bulletin will be updated when additional information becomes available.

Sincerely,

Technical Service

Attachments:

[B652625\[1761929706144\].pdf](#)

[B652625 Recall Notice\[1761929710286\].pdf](#)

[B652625_25V-xyz-PSDI-4-SteeringWheelSwap-FAQ-\(31Oct2025\)](#)

[\[1761929717586\].pdf](#) [B652625\[1761929706144\].pdf](#)

[B652625 Recall Notice\[1761929710286\].pdf](#)

[B652625_25V-xyz-PSDI-4-SteeringWheelSwap-FAQ-\(31Oct2025\)](#)

[\[1761929717586\].pdf](#)

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), All Offering, All Region, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All
BMW SAV (Light Trucks), CC-All



SIB 65 26 25

RECALL 25V-XXX: CHECK DRIVERS FRONT AIR BAG (PSDI-4)

2025-10-31

MODEL

E-Series	Model Description	Production Date
E53	X5 Sports Activity Vehicle	February 19, 1999 – March 31, 2000

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of November 1, 2025, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective October 31, 2025) on certain Model Year 2000 - 2001 BMW vehicles that were produced between February 19, 1999, and March 31, 2000.

This recall campaign involves a sport, or M-sport, steering wheel equipped with the Takata PSDI-4 inflator. Some customers may have switched their original steering wheel which was not affected, to the sport, or M-sport, steering wheel which may include a potentially affected inflator.

The Recall Notice and FAQ have been attached for further information.

The bulletin will be updated when additional information becomes available.

Powered by [Froala Editor](#)

Supporting Materials

[picture_as_pdf B652625 Recall Notice.pdf](#)

[picture_as_pdf B652625_25V-xyz-PSDI-4-SteeringWheelSwap-FAQ-\(31Oct2025\).pdf](#)

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 25V-xxx: Check Drivers Front Air Bag (PSDI-4) – B65 26 25

BMW AG is conducting a Voluntary Safety Recall (effective October 31, 2025) on certain Model Year 2000 - 2001 BMW vehicles that were produced between February 19, 1999, and March 31, 2000.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

**Model Year 2000-2001
BMW X5 SAV
Driver's Front Air Bag Module
Safety Recall 25V-xyz**

Q1. Which models are included in this Safety Recall Campaign?

Certain Model Year 2000-2001 BMW X5 SAV models in the US are potentially affected.

Q2. Which inflator is affected?

This recall campaign involves a sport, or M-sport, steering wheel equipped with the Takata PSDI-4 inflator. Some customers may have switched their original steering wheel which was not affected, to the sport, or M-sport, steering wheel which may include a potentially affected inflator.

Q3. What is the fix?

The driver's front air bag module will be checked and, if a Takata PSDI-4 inflator is found, it will be replaced.

Q4. How long will the repair take?

The repair is FREE. For your convenience, we are currently developing a website to check if you need to have your air bag replaced. When finalized, you will be able to submit images of your VIN and steering wheel. A BMW representative will review your submission and then let you know if a **free** repair at a BMW Center is necessary. If the driver's front air bag module needs to be replaced, it could take approximately one hour. Additional time may be required depending upon your BMW center's schedule.

Q5. How will I be notified of this recall?

Letters will be mailed via First Class mail advising customers of this recall. To ensure BMW of North America, LLC has your most recent contact and vehicle information, please register your vehicle at bmwusa.com/myBMW. Registration is free, and will give you access to factory initiated campaigns and other information specific to your BMW vehicle.

Q6. Do I have to wait for my letter in order to have my vehicle serviced?

Yes. BMW is in the process of developing the necessary tools and procedures for this recall.