

# MACK TRUCKS RECALL ALERT



---

**Subject:** Recall SC0488 Automatic High Beam  
**Recall Number:** SC0488  
**Date:** November 21, 2025  
**Applicable Markets:**  U.S.  Canada  Mexico  Export

---

## **Description**

*Certain Mack Pioneer (PR) and Anthem AN(4) vehicles may be equipped with automatic high beams (AHB) that do not meet the requirements of MVSS 108. Due to errors in identifying certain oncoming vehicles, the headlamp may not switch to low beam lights as expected.*

*High beams that do not automatically switch to low beam may create reduced visibility for other road users, increasing the risk of a crash.*

## **Model and Model Years Affected**

Certain 2025-2026 Pioneer PR and Anthem AN(4) model vehicles manufactured from 10/22/2024 through 11/3/2025.

## **Vehicle Quantities**

301 vehicles (247 US, 46 Canada, 6 Mexico, and 2 Export)

## **Dealer Responsibilities**

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

## **Notification Release Schedule**

- Vehicle list will be posted on the Trucks Dealer Portal 11/21/2025.
- Owner notification letters will be released on or before 1/18/2026.
- Repair instructions will be released once they are available.

## **Contact**

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at [vtna.regulatoryaffairs@volvo.com](mailto:vtna.regulatoryaffairs@volvo.com).