

Genesis Motor America (HMA) has launched Recall Campaign 030G – False Detection of Vehicle /w High Drive Assist Enabled with Remedy Available.

A “stop sale” has been issued on affected new vehicles in retailer's inventory. As required by federal law, retailers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Retailers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Affected Vehicles:

Certain 2023-26MY G90 (RS4) vehicles with Savile Silver colored exterior produced 04/21/2022 – 11/01/2025 built by Hyundai Motor Company ("HMC")

VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

B. Recall Description:

Certain G90 (RS4) vehicles painted in Saville Silver (SSS) and equipped with Highway Drive Assist (HDA)—an advanced driver assistance system that enables semi-autonomous driving on limited-access highways under continuous driver supervision—may, under specific conditions, falsely detect another vehicle entering the lane of travel and apply the brakes without warning. This may occur when HDA is enabled at speeds below approximately 12 mph or when HDA is enabled in conjunction with the Lane Change Assist (LCA) feature, which is activated by the driver signaling a lane change. Sudden, unintended braking can increase the risk of a crash.

Technical Service Bulletin (TSB) 26-01-005G provides instructions to replace the front bumper beam assembly with a revised part to address this condition.

C. New Stock Vehicles at Retailers:

19 – Divided by region as noted below – 19 at retailers.
See attached file for referenced VIN(s) in 'Retailer Stock' tab.

Recall 030G	
Region	G90
CE	1
EA	4
MA	4
MS	0
SC	4
SO	5
WE	4
Other (NH, NL)	0
Total	19

D. Parts Information:

Shipment to Retailer Stock vehicles

Retailers identified with impacted retailer stock inventory (noted above) on 01/20/2026 were shipped a part to their respective retailers. Parts were to arrive starting TODAY, 01/23/2026.

Parts Ordering – VIN required: Retailers will require a valid recall 030G VIN to order the part.

E. Campaign Document:

TSB 26-01-005G

Available on GenesisDealerUSA.com > Service > GMA Tech Info > Campaign

Retailer Notification

Will be provided and posted on Monday @ 12PM PST, 01/26/26.

GenesisDealerUSA.com > Service > GMA Tech Info > Service News

F. Important Notes:

- . Confirm VIN eligibility via WebDCS. Review if any vehicles are currently at retailer's location in retailer stock. **Do not sell any vehicles identified with an open recall until remedy has been applied.**
- . **Follow TSB 26-01-005G** to replace the front bumper beam assembly.
- . **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Genesis guests.
Thank you for your patience and understanding.