



Hyundai Motor America
P.O. Box 2704
Huntington Beach, CA 92647

NHTSA Recall Number: 25V-064

Hyundai Recall Number: 274
(MM/DD/YYYY)

IMPORTANT SAFETY RECALL

Rear Floor Wiring Harness

This is an important Safety Recall.

- **The recall remedy is available.** The recall procedure will be performed on your vehicle at **NO CHARGE** to you.
- Failure to complete this recall repair could increase the risk of injury to occupants during crashes.
- Please contact your nearest Hyundai IONIQ certified dealer to schedule the repair as soon as possible to avoid any inconvenience. To locate and schedule an appointment, please call or visit:

1-855-371-9460 or www.hyundaiusa.com/campaignhome

This notice applies to your 2025 Hyundai IONIQ 5 vehicle, VIN: XXXXXXXXXXXXXXXXXXXX

Dear <FirstName LastName,>

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Hyundai has decided that a defect, which relates to motor vehicle safety, exists in certain 2025 model year Hyundai IONIQ 5 vehicles. Hyundai is initiating Safety Recall 274 to address a condition involving the **Rear Floor Wiring Harness**. Our records indicate that your vehicle, with the VIN listed above, is affected by this recall.

What is the problem?

The rear floor wiring harness may have been produced with insufficient crimping at the rear side airbag connector terminal(s), increasing the risk of an open circuit. An open circuit could trigger an illumination of the air bag warning lamp and prevent the deployment signal in the vehicle's Supplemental Restraint System ("SRS"). A rear side airbag non-deployment may increase the risk of injury to occupants during crashes warranting commanded deployment of the SRS.

What will Hyundai do?

Your Hyundai dealer will inspect the rear floor wiring harness connection(s) and, if necessary, replace the wiring harness. This procedure will be performed at **NO CHARGE** to you.

What should you do?

Please contact your nearest Hyundai IONIQ certified dealer to schedule the recall repair as soon as possible.

The actual time required to perform the inspection will take less than 1 hour, however, your vehicle may be needed longer if the rear floor wiring harness requires replacement. To schedule an appointment with your preferred Hyundai IONIQ certified dealer, please **call 1-855-371-9460** or visit:

1. www.hyundaiusa.com/campaignhome
2. Enter your 17-digit VIN from the top of this letter and click the "Search" button.
3. Click "Schedule Appointment," enter your zip code in the Dealership Locator tool, click "Find a Dealer" button and follow the onscreen prompts to schedule your service appointment.

Additional information

If you have any questions or require further assistance, you may contact the Hyundai Customer Care Center at **1-855-371-9460**.

If you believe that the dealer or Hyundai has failed or is unable to remedy the defect without charge, or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll-free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.NHTSA.gov.


We urge your prompt attention to this important safety matter. We apologize for any inconvenience this may have caused you.

Hyundai Motor America



Hyundai Motor America
P.O. Box 2704
Huntington Beach, CA 92647

NHTSA Recall Number: 25V-064
Hyundai Recall Number: 274




IMPORTANT SAFETY RECALL

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Have you previously paid for this repair?

If you have previously paid for a repair that addresses the problem described in this letter, you may be eligible for a reimbursement. To submit for reimbursement:

1. Visit www.hyundaiusa.com/campaignhome
2. Click this icon in the top right of the webpage: 
3. Click "Contact Us"
4. Click the "Campaign Reimbursement" tile and follow the onscreen directions to submit.

You can also call to obtain additional information at **1-855-371-9460**.

No longer own this vehicle?

You received this notification because U.S. federal regulations require automotive manufacturers to notify last known owners of recalled vehicles based on current owner records. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.