



PETERBILT MOTORS COMPANY
 A **PACCAR** COMPANY
 1700 WOODBROOK STREET P.O. BOX 90208
 DENTON, TEXAS 76205-7864 DENTON TEXAS 76202-5208
 940-591-4000


IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance
 With Federal Law



SAFETY RECALL



000001
 T1 P1

SAFETY RECALL

Recall Notice: 25PBD

IMPORTANT SAFETY RECALL

September 8, 2025

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Subject: 25PBD – Peterbilt 220 Medium Duty Battery Electric Vehicle Dana Cradle Harness Connector
NHTSA Recall Number: 25V182
EXPIRATION DATE: NONE

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in Model Year 2022-2025 220EV vehicles manufactured from 04/30/2021 through 10/16/2023 with a Dana cradle harness. Certain Medium Duty Battery Electric vehicles may experience intermittent continuity in one or more terminal pins of the C40 connector on the cradle harness, resulting in a loss of drive power.

| | |
|----------------------------------|---|
| What is the problem? | Intermittent continuity in the C40 connector may result in a loss of drive power, which may increase the risk of a crash. |
| What will your dealer do? | Your Peterbilt dealer will inspect and replace the cradle harness as necessary. |
| What should you do? | Contact your dealer immediately to schedule an appointment. |

Peterbilt has initiated this recall to remedy the issue at no charge to you. Please contact your Peterbilt dealer to schedule an appointment for these services. To find your Peterbilt dealer, please visit the “Find a Dealer” link at www.Peterbilt.com or scan the QR code. When contacting your Peterbilt dealer, reference the Safety Recall number, NHTSA Recall Number, and VIN(s) listed in this letter. This repair may take up to **13 hours** of labor depending on dealer scheduling.

If you had this repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. Receipts for parts and/or labor are required for consideration of reimbursement. Contact your local Peterbilt dealership for details.

If you require further information about this recall or experience any difficulty in making arrangements for this repair, please contact the Peterbilt Customer Experience Department at PB.Tech.Pubs.Dept@paccar.com.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty.Docs@paccar.com.

We apologize for any inconvenience this procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,
Peterbilt Motors Company

Scan this QR code to open the
Peterbilt Dealer Locator.



Our records indicate that these vehicles are affected by 25PBD and are owned by [REDACTED]

[REDACTED]