



Pure Sports Distributing Inc. DBA: Yamaha of Hawaii 500 Ala Moana Blvd. Ste. 7400 Honolulu, HI 96813

## IMPORTANT SAFETY RECALL NOTICE

This notice applies to your vehicle, VIN: VIN NUMBER Model: MODEL

May 7, 2025

Reference: MRM2501

Dear OWNER NAME:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Yamaha Motor Company, Ltd., has decided that a defect exists in certain 2022-2024 XSR900, 2021-2025 MT-09, 2021-2025 MT-09 SP, 2021-2022 Tracer 9 GT, 2024 Tracer 9 GT+, 2022-2025 MT-10, and 2022-2025 MT-10 SP motorcycles. As a result, Yamaha Motor Company, Ltd., is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

**The reason for this recall:** In affected motorcycles, brushes inside the Throttle Position Sensor (TPS) will slide excessively due to improper Engine Control Unit (ECU) programming. While the motorcycle is driven, this excessive sliding generates abrasion particles that can accumulate on the contact points in the TPS. This illuminates the engine trouble warning light. This can also result in unstable idling and engine stalling, loss of control of the motorcycle, increasing the risk of a crash, injury or death.

**What Yamaha will do:** As a remedy, Yamaha is conducting a recall. Affected motorcycles that were sold and have been operated must have the ECU reprogrammed ("reflashed") and the TPS replaced with a new one, free of charge. Depending on the model, this can take up to an hour and a half to accomplish.

**What you should do:** **Please contact your Yamaha dealer to have this remedy completed as soon as possible.**

If you are unable to return to your original dealer, any authorized Yamaha Motorcycle dealer will perform this service.

If you have had this remedy performed before receiving this letter, you may be entitled to reimbursement for the cost of the remedy. To apply, please contact us with your information, the VIN and details of the remedy.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

**Yamaha of Hawaii  
authorized dealers  
and service  
providers:**

Cycle City Ltd.  
Service Department  
600 Puuloa Rd.  
Honolulu, HI 96819  
(808) 831-2602  
www.cyclecityltd.com

Cycle City Maui  
Service Department  
890 Lower Main St.  
Wailuku, Maui 96793  
(808) 831-2645  
www.cyclecitymaui.com

Kauai Motorsports LLC  
3-1878 Kaunualii Hwy.  
Lihue, HI 96766  
(808) 241-7020  
www.kauaimotorsports.com

Hawaii Rides Inc.  
651 Kilani Ave.  
Wahiawa, HI 96786  
(808) 621-6686

Kiser Motorcycles  
73-4906 Kamanu St.  
Kailua-Kona, HI 96740  
(888) 753-6734  
www.kisermotorcycles.com

**If you need help:** Should your dealer be unable to address your questions or concerns, please contact:

Pure Sports Distributing Inc. DBA: Yamaha of Hawaii  
500 Ala Moana Blvd. Ste. 7400  
Honolulu, HI 96813  
recall@yamahaofhawaii.com

If, your dealer fails or is unable to remedy this defect without charges, or within a reasonable amount of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.nhtsa.gov>.

**If you no longer own this Yamaha:** If you have sold your motorcycle to another party, please email us at [recall@yamahaofhawaii.com](mailto:recall@yamahaofhawaii.com) with the name and address of the new owner, along with the Vehicle Identification Number (VIN).

Thank you for addressing this important matter promptly.

Sincerely,  
Yamaha of Hawaii