



Hyundai Motor America
P.O. Box 2704
Huntington Beach, CA 92647

NHTSA Recall Number: 25V-482
Hyundai Recall Number: 280
[MM/DD/YYYY]

IMPORTANT SAFETY RECALL

Battery System Assembly

This is an important Safety Recall.

- **The recall remedy is available.** The recall procedure will be performed on your vehicle at **NO CHARGE** to you.
- Failure to complete this recall repair could increase the risk of a vehicle fire.
- Due to fire risk, you are strongly advised to **park your vehicle outside and away from structures** until the recall remedy is completed.
- Please contact your nearest Hyundai IONIQ certified dealer to schedule the repair as soon as possible to avoid any inconvenience. To locate and schedule an appointment, please call or visit:

1-855-371-9460 or www.hyundaiusa.com/campaignhome

This notice applies to your 2025 Hyundai IONIQ 5 vehicle, VIN: XXXXXXXXXXXXXXXXXXXX

Dear <FirstName LastName,>

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Hyundai has decided that a defect, which relates to motor vehicle safety, exists in certain 2025 model year IONIQ 5 vehicles. Hyundai is initiating Safety Recall 280 to address a condition involving the **Battery System Assembly** (“BSA”). Our records indicate that your vehicle, with the VIN listed above, is affected by this recall.

What is the Problem?

The BSA in the affected vehicles may contain a high-voltage busbar that was installed with insufficiently tightened retention bolts during supplier assembly. Insufficiently tightened busbar retention bolts could loosen and cause a spark inside the high-voltage battery pack, increasing the risk of a fire. Additionally, loose high-voltage battery pack connections could trigger a voltage sensor error, causing the vehicle to enter a “fail-safe” mode with limited drivability.

What will Hyundai do?

Your Hyundai dealer will inspect the BSA busbar and re-tighten of the retention bolts, as necessary. This procedure will be performed at **NO CHARGE** to you.

What should you do?

Owners are advised to park their vehicles outside and away from structures until the recall remedy is completed.

Please contact your nearest Hyundai IONIQ certified dealer to schedule the recall repair as soon as possible.

The actual time required to perform the repair on your vehicle will take less than 5 hours, however, your vehicle may be needed longer. To schedule an appointment with your preferred Hyundai IONIQ certified dealer, please call **1-855-371-9460** or visit:

1. www.hyundaiusa.com/campaignhome
2. Enter your 17-digit VIN from the top of this letter and click the “Search” button.
3. Click “Schedule Appointment,” enter your zip code in the Dealership Locator tool, click “Find a Dealer” button and follow the onscreen prompts to schedule your service appointment.

Additional Information

If you have any questions or require further assistance, you may contact the Hyundai Customer Care Center at 1-855-371-9460.

If you believe that the dealer or Hyundai has failed or is unable to remedy the defect without charge, or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll-free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.NHTSA.gov.


Your safety is our top priority. We urge you to take prompt action to address this safety recall for your vehicle by scheduling the necessary service as soon as possible. We sincerely apologize for any inconvenience this may cause and appreciate your attention to this matter.

Hyundai Motor America



Hyundai Motor America
P.O. Box 2704
Huntington Beach, CA 92647

NHTSA Recall Number: 25V-482
Hyundai Recall Number: 280



IMPORTANT SAFETY RECALL

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Have you previously paid for this repair?

If you have previously paid for a repair that addresses the problem described in this letter, you may be eligible for reimbursement. To submit for reimbursement:

1. Visit www.hyundaiusa.com/campaignhome
2. Click this icon in the top right of the webpage 
3. Click "Contact Us"
4. Click the "Campaign Reimbursement" tile and follow the onscreen directions to submit

You can also call to obtain additional information at **1-855-371-9460**.

No longer own this vehicle?

You received this notification because U.S. federal regulations require automotive manufacturers to notify last known owners of recalled vehicles based on current owner records. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.