

IMPORTANT SAFETY

Mercedes-Benz USA, LLC
A Mercedes-Benz Group AG
Company
One Mercedes-Benz Drive
Sandy Springs, GA 30328
Phone: (800) 367-6372

This notice applies to your vehicle, VIN: [REDACTED]

Replace High Voltage

MBUSA ID: 2025080004, NHTSA Recall ID: 25V487

- The remedy is now available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided **FREE** of charge.

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain model year 2022-2023 EQB 4MATIC vehicles. **Our records indicate that your vehicle is included in the affected population.**



What is the issue?

In early 2025 we contacted you regarding recall campaign number 25V050 and/or 25V894 to advise you of a needed software update for the high voltage battery in your EQB vehicle. MBAG found that the software update that was carried out as part of the prior recall did not remove the fire risk associated with the recall. MBAG found that on certain vehicles, the high voltage battery may fail due to an internal short circuit of a battery cell, which could lead to a vehicle fire while parked or driving.

In addition, in late 2025 you were notified of the above recall campaign number 25V487 to advise you that the bus bar in the high voltage battery may not be secured with the correct screws, which can cause the system to have a sudden loss of drive power without warning. A loss of drive power can increase the risk of a crash.

Both issues associated with the recall campaign numbers 25V050, 25V894 and 25V487 will be remedied with a replacement of the high voltage battery.

What will your Mercedes-Benz Dealer do?

An authorized Mercedes-Benz dealer will replace the high-voltage battery on the affected vehicles. **This vehicle repair will be provided at no cost to you.** Until the remedy is performed on your vehicle, the maximum state of charge for your vehicle's high-voltage battery **must not** exceed 80%. This is an important measure to help protect the high-voltage battery in your vehicle until the remedy is performed. Out of an abundance of caution, customers are additionally advised to **park their vehicles outside**. Please be advised that you may continue to drive your vehicle, provided that the maximum state of charge **does not exceed** 80%, and the affected vehicle(s) is parked outside when not in use.



Don't wait. Find an authorized Mercedes-Benz dealer near you at www.mbusa.com/recall and schedule the recall repair right away.



IMPORTANT SAFETY

Mercedes-Benz USA, LLC
A Mercedes-Benz Group AG
Company
One Mercedes-Benz Drive
Sandy Springs, GA 30328
Phone: (800) 367-6372

While the repair time can be less than **7 hours**, your dealer can provide you with a better estimate of the overall time for this visit. As a matter of normal service process, the authorized Mercedes-Benz dealer will also check for other repair measures that might be applicable to your vehicle, which may increase the required working time. You will not be charged for other services or repairs unless so requested.



Steps to take:

- If you have not already had your vehicle repaired for this recall, find your nearest authorized Mercedes-Benz dealer at www.mbusa.com/recall to schedule your recall repair.
- Please mention you are scheduling an appointment for Mercedes-Benz recall **2025080004**.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.

We apologize for any inconvenience this may have caused and look forward to taking care of this important safety recall immediately.

Sincerely,
Mercedes-Benz USA



What if I no longer own or drive the vehicle or would like to update my contact information?

In the event you need to update your contact information or have updates concerning the vehicle, please visit www.mbusa.com/recall (or scan the QR Code to the left), submit your VIN using the VIN recall lookup tool, and complete the "Recall Contact Information" section on the website. If possible, please provide any contact information of the current owner/driver so we can contact them.

Additional Information for Owners:

A VIN-based recall lookup tool is available at www.mbusa.com/recall, which can be used to check whether a vehicle has been subject to a safety recall, or have had the remedy performed. Should you have any questions or encounter any difficulty regarding this recall, please contact an authorized Mercedes-Benz dealer.

Should an authorized Mercedes-Benz dealer be unable to address your concerns, please contact us at **1-(800) FOR-MERCEDES (1-800-367-6372)**. We are always happy to hear from you.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, Pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171); or go to <https://www.nhtsa.gov>.

Don't wait. Find an authorized Mercedes-Benz dealer near you at www.mbusa.com/recall and schedule the recall repair right away.

